IBEX Command Approval Checklist Rev 16e removes the Moon in Lo FOV section.

Orbit	426	Special Ops	None		
14 R _E asc. Date/Time	11/3/2018 20	:54:41	15 R _E asc. Date/Time	11/3/2018 22:	39:00
Apogee	11/7/2018 21:07:30	Maneuver Window Start	11/7/2018 11:08:07	Maneuver Window End	11/8/2018 07:08:09
Apogee Target	_	485000000000000 914200000000000	00 targetY:-0.618 00	312199999999995	
15 R _E desc. Date/Time	11/11/2018 1	8:47:50	14 R _E desc. Date/Time	11/11/2018 20	:27:21
Perigee	11/12/2018 06:29:24	Maneuver Window Start	11/11/2018 20:58:08	Maneuver Window Stop	11/12/2018 16:32:19
Perigee Target		125899999999999 959000000000000	05 targetY:-0.667 02	7931000000000005	
Eclipse	No	Eclipse Start		Eclipse End	
Sun Mnvr	No	Apogee/Perigee		Sun Angle at DESCENDING	
Approved Version	IBEX_2018_307	_o0426a_v001.s	scr		_

Activity	Command Checks	Date Done	Done By
Supporting Materials	 IBEX_CrossingTimes_<date>_v00x.txt on SFTP at /Archive-Incoming/IBEXIncoming/FDG/PredictedEphemeris/Orbit Events/.</date> Orbit Events File on SFTP at /IBEXOutgoing/MOC/Moc-Soc/oef/. Command Constraint Violations Report on SFTP at /IBEXOutgoing/MOC/Moc-Soc/cvr/. Contacts this orbit Orbit_oXXX.txt included in the ATS approval email. Science Tasking File at /Archive-Incoming/IBEXIncoming/MOC/Soc-Moc/stf/. Merged ATS at http://ibex.unh.edu/cgi-bin/ats.cgi. 	10/23/18	NGA
Sun Maneuvers	 Additional contacts should not be planned to support IBEX Sun Precession Maneuvers due to star tracker outages. The standard apogee and perigee contacts should be used to verify that a maneuver has occurred. If it is not possible to plan one of the standard contacts after the star tracker outage is down to 50% and a valid quaternion reading can be made to verify the maneuver, the coarse Sun sensor angle and the thruster pulse count will be used to determine a) whether a maneuver took place, and b) whether the pointing after the maneuver is as expected +/- 2 degrees. 	N/A	
	 The nominal off-Sun pointing constraint is 7.25 degrees. Based on the missed maneuver in orbit 114, the payload team has determined that there is no hardware risk associated with off-Sun pointing up to angles of at least 13 degrees. There is a higher background noted in the data starting at around 9.5 degrees off Sun pointing. 		
File Input Check	 Current OEF inputs are Forecast STF, last orbit's OEF & latest predictive ephemeris. ATS inputs are this orbit's OEF & STF. (And ABS if present.) ATS filename is of the format IBEX_yyyy_doy_o0xxxa_v0zz.scr. where IBEX is capitalized, yyyy is the year, doy is the day of year, xxx is the 3-digit orbit number and zz is the 2-digit version number. Any special operations ATSs will have another designation between the orbit number and version number (i.e. *o0186a_hgc_v001 for the Hi gain curve). 	10/23/18	NGA

Calinaga	1.	Check OEF for eclipses during the orbit.	N/A	
Eclipses	2.	Verify long eclipse flag start & stop times reflect Ryan Tyler's recommendations based on his	N/A	
		eclipse diagnostic tool. Suggestions made by Ryan after the use of this tool trump the general		
		guidelines below. (Please note, specific timing may shift if the recommendations are relative to		
		eclipse timing. For example, it may say set LE flag to false X hours after the end of the eclipse		
		with a given FALSE time suggested. If the eclipse timing changes as the ephemeris becomes		
		more refined, this command time may shift.)		
	3.	Verify no contacts planned during an eclipse. Note: If in conflict, the eclipse diagnostic		
		recommendations will trump the general guidelines below.		
		 Verify transmitter OFF from 30 minutes before eclipse start through the end of the eclipse. 		
		b. For an eclipse where the long eclipse flag is set, schedule a SOH contact directly		
		following the end of the eclipse (or per Ryan's assessment).		
		c. Set the LE flag according to Ryan's assessments.		
	4.	Verify no maneuver planned during an eclipse. Note: If in conflict, the eclipse diagnostic		
		recommendations will trump the general guidelines below.		
		 Verify no maneuver or cat bed heaters on from 3 hours before eclipse start through 3 hours after eclipse end. 		
		b. Verify no maneuver or cat bed heaters are on while the long eclipse flag is set.		
	5.	Verify the following additional constraints (from battery balancing section).		
		 Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to FALSE. 		
		b. Verify P/L is in HVSTANDBY or HVENG.		
		c. Verify no charging cycle within 2 hours of ASCENDING or DESCENDING macro		
		execution.		
		This applies to all eclipses, not just moderate or long eclipses.		
Contact	1.	Verify STX on/off times, downlink rate against Orbit_oXXX.txt file.	10/23/18	NGA
Commands	2.	Verify contacts in the previous ATS have not been duplicated.	10/20/10	110,1
	3.	Verify all currently planned contacts in Orbit_xxx.txt are in the ATS.		
	4.	Verify each contact contains the following 5 commands.		
		SetRelay stx,on		
		 SetDownlink2K (2K, 40K, 64K, 160K, or 320K) 		
		 SetBilevelOutputControlReg STXMODE_Strobe,ON 		
		SetBilevelOutputControlReg COHERENT,ON		
	_	SetRelay stx,off		
	5.	If contact is near an eclipse a. Verify transmitter OFF from 30 minutes before eclipse start through 30 minutes after		
		eclipse end.		
		b. If additional transmitter constraints exist, they will be captured in Ryan's		
		recommendations.		
	6.	If an APL contact is being used for an SSR Dump, the data rate should be at least 160 ksps & the SSR DUMP NEW command should be included in the contact commands. Commands in Orange		
		should only be sent if the SSR pointers need to be reset this perigee. These commands should		
		be separated by 2s and occur 2s after the SSR_DUMP_NEW command.		
1		SetRelay stx,on		
		SetDownlink2K		
		 SetBilevelOutputControlReg STXMODE_Strobe,ON 		
		SetBilevelOutputControlReg COHERENT,ON		
		SetDownlink320K		
		SSR_DUMP_NEW SSR_ST_RR_STR_STR_STR_STR_STR_STR_STR_ST		
		SSR_SET_RD_PTR 6500 SSR_SET_NUTE BTR 6500		
		• SSR_SET_WRT_PTR 6500		
		SetRelay stx,off		

SC State	1.	Transition to Science state will be first command of each ATS (at 14 Re).	10/23/18	NGA
Science:		 SetScState science \$TIME=2018/11:03:20:54:51 		
arc a	2.	Lo science mode will be the next command (at 14 Re).		
		LO SCIENCE MODE NORMAL		
	3.	Verify no transition to Science again at the end of the ATS. The ATS commands go from 14 Re to		
		14 Re in each orbit.		
	4.	Verify the transition to Science commands for this orbit are not part of the previous ATS using		
		http://ibex.unh.edu/cgi-bin/ats.cgi.		
	5.	Verify that the beginning of this ATS does not overlap with the end of the previous orbit's ATS		
		using http://ibex.unh.edu/cgi-bin/ats.cgi.		
Dayload	1.	Verify w/ Crossing Times report that it occurs about 15 Re ascending. The arc a ASCENDING	10/23/18	NGA
Payload Mode		commands can start any time at or above 15 Re ascending.	10/23/10	NGA
HVSCI:	2.	Verify commanding takes ~ 24 minutes.		
arc a		 ASCENDING_PL1 \$TIME=2018/11:03:22:39:05 		
aica		ASCENDING_HI		
		SET_PARAMETER 1, TLM_RATE_SOH		
		SET_PARAMETER 4, HV_STEP_DWELL		
		SET_PARAMETER 3, HV_STEP_FRAC		
		HI COL NEG LVL 1400		
		• CEU HI CEM 1 LVL 1780		
		• CEU_HI_CEM_2_LVL 1780		
		• CEU_HI_CEM_3_LVL 1780		
		CEU HI CEM 4 LVL 1900		
		SET_PARAMETER 0, TLM_RATE_SOH		
		ASCENDING PL2		
		ASCENDING PL1		
		ASCENDING LO		
		• ASCENDING_PL2 \$TIME=2018/11:03:23:02:53		
	1.	Payload DESCENDING commands end 1.5h before thruster enable.		
Payload	2.	Verify commands take ~23 minutes to execute.	10/23/18	NGA
Mode		DESCENDING_PL1 \$TIME=2018/11:07:09:12:09		
HVSTANDBY		DESCENDING_LO		
: arc a		ASCENDING_LO		
		DESCENDING_PL1		
		DESCENDING_FET DESCENDING HI		
		 DESCENDING_RI DESCENDING_PL2 \$TIME=2018/11:07:09:34:59 		
	1.	Spacecraft Housekeeping command occurs 1h before thruster enable.		
SC State	1.		10/23/18	NGA
HK : arc a		SetScState housekeeping \$TIME=2018/11:07:10:08:09		

10/23/18 NGA	Precession Maneuver: Apogee' sequence below. Verify Thruster enable command occurs within STF maneuver window. Verify cat bed heaters come on 55 min before burn. Actable 5 N. HTR.ON STIME=2018/11:07:10:33:07 Verify Kalman Filter input select is ground command & estimator update is disabled. SettEnputSelect 6ND, CMD, 0, 0, 0, 0, 0 SetEstUpdateEnables ENABLE, DISABLE Verify in FC mode Burn. SetterMode burn Compare SetInrDir: no ATS with pointing as defined in the Forecast STF & verify the vectors match. SetInrDir: -0.73485-0.6181220.279142 target2: -0.279142000000000000000000000000000000000000	Γ	_		T	1
N/A	2. Verify Thruster enable command occurs within STF maneuver window. 3. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. 4. Verify cat bed heaters come on 55 min before burn. 5. Verify Namen Filter input select is ground command & estimator update is disabled. 5. SettStlpdateEnables ENABLE, DISABLE 6. Verify in FC mode Burn. 7. Compare SetIrnDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. 8. SetInDIr -0.73485.0618122.0.279142 1	Inertial	1.	Use this command sequence if an apogee inertial maneuver is used, otherwise skip to the 'Sun	10/23/18	NGA
N/A	3. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. 4. Verify cat bed heaters come on 55 min before burn. 6. CATBED_SN_HTR,ON \$TIME=2018/11:07:10:13:07 5. Verify Kalman Filter input select is ground command & estimator update is disabled. 6. Verify in FC mode Burn. 7. Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. 8. SetEreMode burn 7. Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. 8. Verify inertial maneuver chosen. 9. SetInraget X: -0.79142000000000000000000000000000000000000	Maneuver:				
N/A	4. Verify cat bed heaters come on 55 min before burn. • CATBED_5N_HTR,ON \$TIME=2018/11:07:10:13:07 5. Verify Kalman Filter input select is ground command & estimator update is disabled. • SetKFInputSelect GND_CMD, 0, 0, 0, 0 • SetEstUpdateEnables ENABLE, DISABLE 6. Verify in FC mode Burn. • SetFcMode burn 7. Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. • SetInrDir -0.73485,0.618122,-0.279142 targetX:-0.73485000000000000000000000000000000000000	Apogee				
N/A	* CATBED_SN_HTR,ON_STIME=2018/11:07:10:13:07 5. Verify Kalman Filter input select is ground command & estimator update is disabled. * SettKripputSelect GND_CMD, 0, 0, 0, 0 * SetEstUpdateEnables ENABLE, DISABLE 6. Verify in FC mode Burn. * SetErCMode burn 7. Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. * SetInrDir -0.73485,-0.618122,-0.279142					
N/A	5. Verify Kalman Filter input select is ground command & estimator update is disabled. • SettKFInputSelect GND_CMD_0, 0, 0, 0 • SettSttUpdateEnables ENABLE, DISABLE 6. Verify in FC mode Burn. • SetToMode burn 7. Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. • SetInrDir -0.73485_0.6181220.279142 targetX: -0.73485000000000000000000000000000000000000		٦.			
N/A	SetKFInputSelect GND_CMD, 0, 0, 0 SetEstUpdateEnables ENABLE, DISABLE 6. Verify in PC mode Burn. SetFcMode burn 7. Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. SetInrDir -0.73485,-0.618122,-0.279142 targetX: -0.73485000000000000000000000000000000000000		5			
N/A	SetEstUpdateEnables ENABLE, DISABLE Verify in FC mode Burn SetErMode burn Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. SetInrDir -0.73485,-0.618122,-0.279142 targetX:-0.73485000000000000000000000000000000000000		٦.			
N/A	6. Verify in FC mode Burn. • SettcMode burn 7. Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. • SetInrDir -0.73485,-0.618122,-0.279142 targetX:-0.73485000000000000000000000000000000000000					
N/A	SetFcMode burn Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. SetInrDir -0.73485,-0.618122,-0.279142		6			
N/A	7. Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match. • SetInrDir -0.73485,-0.618122,-0.279142 targetX:-0.73485000000000000000000000000000000000000		0.	·		
N/A	match. SetInrDir -0.73485,0.618122,-0.279142 targetX:-0.73485000000000000000000000000000000000000		7			
N/A	Sun Set		' '			
N/A	targetX:-0.73485000000000000000000000000000000000000					
N/A	target Z: -0.279142000000000000 8. Verify inertial maneuver chosen.					
N/A	8. Verify inertial maneuver chosen. • SettrTarget ACS_INERTIAL 9. Verify thrust time set to 11 min. • SetThrustTime 660 10. Verify thruster enable command matches RepointingManeuverStart time in OEF. • SetThrustEnable ENABLE \$TIME=2018/11:07:11:08:07 • RepointingManeuverStart 2018-11-07T11:08:07 11. Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0. • SetThrustEnable DISABLE \$TIME=2018/11:07:11:18:07 • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. • SetKFInputSelect STA_PCT_VALID, 43,28,33,48 • SetFcMode Mission Sun aneuver Apogee 1. Use this command sequence in the event of an apogee Sun maneuver. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify in FC mode Burn and Sun target. • SetFcMode burn					
N/A	SetLrTarget ACS_INERTIAL 9. Verify thrust time set to 11 min.		R			
N/A	9. Verify thrust time set to 11 min. • SetThrustTime 660 10. Verify thruster enable command matches RepointingManeuverStart time in OEF. • SetThrustEnable ENABLE \$TIME=2018/11:07:11:08:07 11. Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0. • SetThrustEnable DISABLE \$TIME=2018/11:07:11:18:07 • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. • SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 • SetKFInputSelect STA_PCT_VALID, 43,28,33,48 • SetFcMode Mission 1. Use this command sequence in the event of an apogee Sun maneuver. 2. Verify Thruster enable command occurs within STF maneuver window. 3. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. • CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. • SetFcMode burn		0.	· · · · ·		
N/A	SetThrustTime 660 10. Verify thruster enable command matches RepointingManeuverStart time in OEF. SetThrustEnable ENABLE \$TIME=2018/11:07:11:08:07 RepointingManeuverStart 2018-11-07T11:08:07 RepointingManeuverStart 2018-11-07T11:08:07 RepointingManeuverStart 2018-11-07T11:08:07 RepointingManeuverStart 2018-11-07T11:08:07 RepointingManeuverStart 2018-11-07T11:08:07 SetThrustEnable DISABLE \$TIME=2018/11:07:11:18:07 SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. 3. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. SetFcMode burn		9			
N/A	10. Verify thruster enable command matches RepointingManeuverStart time in OEF. • SetThrustEnable ENABLE \$TIME=2018/11:07:11:08:07 • RepointingManeuverStart 2018-11-07T11:08:07 11. Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0. • SetThrustEnable DISABLE \$TIME=2018/11:07:11:18:07 • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. • SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 • SetKFInputSelect STA_PCT_VALID, 43,28,33,48 • SetFcMode Mission Sun accession aneuver Apogee Apogee 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. 2. Verify on eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. • CATBED_SN_HTR,ON 5. Verify in FC mode Burn and Sun target. • SetFcMode burn		١.	•		
N/A	SetThrustEnable ENABLE \$TIME=2018/11:07:11:08:07 RepointingManeuverStart 2018-11-07T11:08:07 11. Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0. SetThrustEnable DISABLE \$TIME=2018/11:07:11:18:07 SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify on eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. SetFcMode burn		10			
N/A	RepointingManeuverStart 2018-11-07T11:08:07 11. Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0. SetThrustEnable DISABLE \$TIME=2018/11:07:11:18:07 SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission 1. Use this command sequence in the event of an apogee Sun maneuver. Apogee Apogee Apogee 1. Use this command sequence in the event of an apogee Sun maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. CATBED_5N_HTR,ON Verify in FC mode Burn and Sun target. SetFcMode burn		10.			
N/A	11. Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0. SetThrustEnable DISABLE \$TIME=2018/11:07:11:18:07 SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. CATBED_5N_HTR,ON Verify in FC mode Burn and Sun target. SetFcMode burn					
N/A	to 0. SetThrustEnable DISABLE \$TIME=2018/11:07:11:18:07 SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. CATBED_5N_HTR,ON Verify in FC mode Burn and Sun target. SetFcMode burn		11			
N/A	SetThrustEnable DISABLE \$TIME=2018/11:07:11:18:07 SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. CATBED_5N_HTR,ON Verify in FC mode Burn and Sun target. SetFcMode burn					
N/A	SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission Sun eccession aneuver Apogee 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. CATBED_5N_HTR,ON SetFcMode burn N/A N/A SetFcMode burn					
N/A	SetThrustTime 0 12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission Sun eccession aneuver Apogee 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. CATBED_5N_HTR,ON Verify in FC mode Burn and Sun target. SetFcMode burn					
N/A	12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission. • SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 • SetKFInputSelect STA_PCT_VALID, 43,28,33,48 • SetFcMode Mission Sun eccession aneuver Apogee 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. • CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. • SetFcMode burn					
N/A	Sun excession aneuver Apogee SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:07:11:33:17 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. SetFcMode burn		12.			
N/A	Sun excession aneuver Apogee SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. SetFcMode burn					
N/A	Sun ecession aneuver Apogee 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. • CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. • SetFcMode burn					
N/A	Sun ecession aneuver Apogee 1. Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. • CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. • SetFcMode burn					
N/A	2. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable. • CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. • SetFcMode burn	0	1		N1/A	
	3. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. 4. Verify cat bed heaters powered on 55 min before thruster enable. • CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. • SetFcMode burn				N/A	
	4. Verify cat bed heaters powered on 55 min before thruster enable. • CATBED_5N_HTR,ON 5. Verify in FC mode Burn and Sun target. • SetFcMode burn					
	CATBED_5N_HTR,ON Verify in FC mode Burn and Sun target. SetFcMode burn					
J. J.	5. Verify in FC mode Burn and Sun target.SetFcMode burn	. Apogee				
			5.	Verify in FC mode Burn and Sun target.		
	Sett rTarget ACS STIN			SetFcMode burn		
	- Jeth laiget Ac3_JOIN			SetLrTarget ACS_SUN		
	C Marife the most time and the AC main		6.	Verify thrust time set to 16 min.		
	6. Verify thrust time set to 16 min.			SetThrustTime 960		
	SetThrustTime 960		7.	Verify thruster enable command matches SunMvrBegin time in OEF.		
	SetThrustTime 9607. Verify thruster enable command matches SunMvrBegin time in OEF.			SetThrustEnable ENABLE		
	SetThrustTime 960			• CupMurDogin		
	 SetThrustTime 960 7. Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin 			· · · · · · · · · · · · · · · · · · ·		
1	 SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set 		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set		
	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission.		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission.		
	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE		
	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE SetHTRCmd CATBED_5N_HTR,OFF		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE • SetHTRCmd CATBED_5N_HTR,OFF		
	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0		
	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 SetFcMode Mission		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0 • SetFcMode Mission		
10/23/18 NGA	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 SetFcMode Mission Spacecraft Science commands occur ~1h after thruster Disable.	SC State		Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0 • SetFcMode Mission Spacecraft Science commands occur ~1h after thruster Disable.	10/23/18	NGA
10/23/18 NGA	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE SetThrustTime 0 SetThrustTime 0 SetFcMode Mission 1. Spacecraft Science commands occur ~1h after thruster Disable. SetScState science \$TIME=2018/11:07:12:23:13 NG	SC State Science :		Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0 • SetFcMode Mission Spacecraft Science commands occur ~1h after thruster Disable. • SetScState science \$TIME=2018/11:07:12:23:13	10/23/18	NGA
			6.	 SetFcMode burn SetLrTarget ACS_SUN Verify thrust time set to 16 min. SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE 		
	6. Verity thrust time set to 16 min.			SetThrustTime 960		
			7.	Verify thruster enable command matches SunMyrBegin time in OEF.		
	SetThrustTime 960			SetThrustEnable ENABLE		
	SetThrustTime 9607. Verify thruster enable command matches SunMvrBegin time in OEF.			a CunMurDagin		
	 SetThrustTime 960 7. Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE 			• Sunivivi Begin		
	 SetThrustTime 960 7. Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin 		8.	· · · · · · · · · · · · · · · · · · ·		
	 SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set 		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set		
	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission.		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission.		
	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE		
	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE SetHTRCmd CATBED_5N_HTR,OFF		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE • SetHTRCmd CATBED_5N_HTR,OFF		
	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0		8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0		
	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 SetFcMode Mission			Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0 • SetFcMode Mission		
10/23/18 NGA	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 SetFcMode Mission Spacecraft Science commands occur ~1h after thruster Disable.	SC State		Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0 • SetFcMode Mission Spacecraft Science commands occur ~1h after thruster Disable.	10/23/18	NGA
10/23/18 NGA	SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE SunMvrBegin Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. SetThrustEnable DISABLE SetHTRCmd CATBED_5N_HTR,OFF SetThrustTime 0 SetFcMode Mission Spacecraft Science commands occur ~1h after thruster Disable. SetScState science STIME=2018/11:07:12:23:13	SC State Science :		Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission. • SetThrustEnable DISABLE • SetHTRCmd CATBED_5N_HTR,OFF • SetThrustTime 0 • SetFcMode Mission Spacecraft Science commands occur ~1h after thruster Disable. • SetScState science \$TIME=2018/11:07:12:23:13	10/23/18	NGA

	1 Verify payload ACCENDING commands begin at least 1.5 began offer throughout DICARI C		
Payload	 Verify payload ASCENDING commands begin at least 1.5 hours after thruster DISABLE. Verify commands take ~24 minutes to execute. 	10/23/18	NGA
Mode	ASCENDING PL1 \$TIME=2018/11:07:12:53:13		
HVSCI:	ASCENDING_H		
arc b	SET PARAMETER 1, TLM RATE SOH		
	SET_PARAMETER 4, HV_STEP_DWELL		
	SET PARAMETER 3, HV STEP FRAC		
	• HI COL NEG LVL 1400		
	• CEU HI CEM 1 LVL 1780		
	• CEU HI CEM 2 LVL 1780		
	• CEU HI CEM 3 LVL 1780		
	• CEU HI CEM 4 LVL 1900		
	SET PARAMETER 0, TLM RATE SOH		
	ASCENDING PL2		
	ASCENDING PL1		
	ASCENDING LO		
	ASCENDING PL2 \$TIME=2018/11:07:13:17:01		
Payload	Verify w/ Crossing Times report that it occurs about 15 Re descending. The arc b DESCENDING		
Mode	commands can complete any time at or above 15 Re descending.	10/23/18	NGA
HVSTANDBY			
: arc b	• DESCENDING PL1 \$TIME=2018/11:11:18:21:45		
	DESCENDING LO		
	ASCENDING PL2		
	DESCENDING PL1		
	DESCENDING HI		
	 DESCENDING_PL2 \$TIME=2018/11:11:18:44:35 		
SC State	Verify with Crossing Times report that Transition to Housekeeping state occurs at 14 Re desc (or	10/23/18	NGA
HK : arc b	an hour before the maneuver if the maneuver occurs less than 1 hour after 14 Re desc).	10/23/10	NGA
	SetScState housekeeping \$TIME=2018/11:11:19:57:20		

Inertial	1.	Use this command sequence if a perigee inertial maneuver is used, otherwise skip to the 'Sun	10/23/18	NGA
Maneuver :		Precession Maneuver : Perigee' sequence below.		
Perigee	2.	Verify no eclipse occurs from cat bed heater on through set FC mode Mission.		
J	3.	Verify cat bed heaters come on 55 min before burn.		
		• CATBED_5N_HTR,ON \$TIME=2018/11:11:20:03:08		
	4.	Verify in Housekeeping state.		
	5.	Verify Kalman Filter input select is ground command & estimator update is disabled.		
	٦.	SetKFInputSelect GND_CMD, 0, 0, 0, 0		
	6	SetEstUpdateEnables ENABLE, DISABLE Verify in FC mode Burn.		
	6.	•		
	_	SetFcMode burn Out Divination and the first ATC of the second s		
	7.	Compare SetInrDir in ATS with target vector in the Forecast STF & verify the vectors match.		
		• SetInrDir -0.681259,-0.667931,-0.29959		
		targetX:-0.6812589999999995 targetY:-0.6679310000000005		
		targetZ:-0.2995900000000002		
	8.	Verify inertial maneuver chosen.		
		SetLrTarget ACS_INERTIAL		
	9.	Verify thrust time set to 11 min.		
		SetThrustTime 660		
	10.	Verify thruster enable command matches RepointingManeuverStart time in OEF.		
		SetThrustEnable ENABLE \$TIME=2018/11:11:20:58:08		
		RepointingManeuverStart 2018-11-11T20:58:08		
	11.	Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set		
		to 0.		
		SetThrustEnable DISABLE \$TIME=2018/11:11:21:08:08		
		• CATBED_5N_HTR,OFF		
		SetThrustTime 0		
	12	Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission.		
	12.	SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/11:11:21:23:18		
		 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFcMode Mission 		
	_			
Sun	1.	Use this command sequence in the event of a perigee Sun maneuver.	N/A	
Precession	2.	Verify Thruster enable command occurs within STF maneuver window.		
Maneuver :	3.	Verify no eclipse occurs from cat bed heater on through set FC Mode Mission. Verify cat bed heaters come on 55 min before burn.		
Perigee	4.	CATBED_5N_HTR,ON \$TIME=2018/10:25:01:12:41		
	5.	Verify in FC mode Burn and Sun target.		
	٦.	SetFcMode burn		
		SetLrTarget ACS_SUN		
	6.	Verify thrust time set to 16 min.		
	٥.	SetThrustTime 960		
	7.	Verify thruster enable command matches SunMvrBegin time in OEF.		
	′ ′	SetThrustEnable ENABLE \$TIME=2018/10:25:02:07:41		
		• SunMvrBegin 2018-10-25T02:07:41		
	8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set		
] .	to 0, FC mode Mission.		
		SetThrustEnable DISABLE \$TIME=2018/10:25:02:22:41		
		SetHTRCmd CATBED 5N HTR,OFF		
		SetThrustTime 0		
		SetFcMode Mission		
L	1		I	<u> </u>

IBEX Command Approval Checklist K. Fairchild

				Rev	16e
Last u	pdate	09/12	2/201	8	

Battery Cell Balancing	1. 2. 3. 4. 5. 6. 7.	There will be battery cell balancing every 2 out of 3 orbits. Battery cell balancing this orbit? Y Verify charging cycle (Long eclipse flag=TRUE) is 90 minutes long. Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to FALSE. Verify P/L is in HVSTANDBY or HVENG. Verify no charging cycle within 2 hours of ASCENDING or DESCENDING macro execution. Verify no charging cycle within 1 hour of maneuver. Verify no charging cycle during an eclipse.	10/23/18	NGA
Cmd Violation	1.	Review CCVR. If you have any questions Reply All to the ATS Approval email and ask the team.	10/23/18	NGA

Activity		Anomaly Response : Non-nominal burn	Date Completed	Completed By
	•	If the maneuver has not occurred or the spacecraft pointing as designated by either the star tracker or coarse Sun sensor is off by more than 2 degrees from the expected pointing, an anomaly has occurred.		
		If the spacecraft is in Contingency state all stored commands are flushed from the command queue. Follow standard anomaly process. **Title On the Command of the Comm		
		If the Sun maneuver did not occur and the spacecraft is in either Science or Housekeeping state follow the steps below. (1)		
		 If a partial Sun maneuver has occurred and the spacecraft is in either Science or Housekeeping state follow the steps below. 		
	•	Please note that there is no anticipated hardware damage associated with exceeding the 12.5 degree constraint; this constraint is in place because we should not exceed the largest pointing achieved thus far in the mission.		
	1.	If the payload is in HVSTANDBY, LVENG or OFF, and there are no commands loaded to bring it to HVSCI voltages, no operational pointing constraints will be violated. Follow standard anomaly process.		
	2.	If the payload is in HVSCI mode or there are uploaded commands to bring the payload to HVSCI mode,		
		 a. Determine current off Sun pointing. If the off Sun angle has already exceeded 12.5 degrees, the MOC should notify the MOM and immediately send the DESCENDING command suite in real-time, as described below. If this cannot be done in the contact where the pointing anomaly was discovered, another contact will be planned as soon as possible to execute these commands. @CEU_MACRO_EXEC_DESCENDING_PL1 (< 1 min) 		
		<pre>@CEU_MACRO_EXEC DESCENDING_LO (~ 10 min) @CEU_MACRO_EXEC DESCENDING_HI (~ 8 min) @CEU_MACRO_EXEC DESCENDING_PL2 (< 1 min) Please note: The only scenario where hitting 12.5 degrees is expected is when a</pre>		
		perigee Sun precession maneuver is completely missed after an inertial apogee maneuver which occurs late in the maneuver window (near apogee + 10 hours). b. If current Sun pointing is below 12.5 degrees, the ISOC should input ST Sun-		
		pointing angle into ibex_rotate to determine the Sun angle at the time of DESCENDING. Sun-Angle at payload DESCENDING		
		c. If 12.5 degrees is not exceeded by the time of DESCENDING, no payload-specific action is needed for this arc. Follow standard anomaly response process.		
		 If 12.5 degrees is exceeded by the time of DESCENDING, a new command set should be sent. 		
		 The ISOC will generate the new STF which has the DESCENDING commands executing early such that 12.5 degrees is not exceeded while the payload is in HVSCI. 		
		 ii. The MOC will create an associated ATS. iii. Approval is needed by the MOM, MOC & ISOC prior to upload. iv. The MOC will assess whether an additional pass is needed in order to upload the commands prior to exceeding the 12.5 degree constraint. The 		
		onboard DESCENDING commands do not need to be deleted.		