## IBEX Command Approval Checklist Rev 16b incorporates post-ST anomaly changes and resetting the SSR pointers in an APL contact.

Orbit	394	Special Ops	ISN Pointing, S	ISN Pointing, Short Eclipse			
14 R <sub>E</sub> asc. Date/Time	1/17/2018 13	:20:23	15 R <sub>E</sub> asc. Date/Time	1/17/2018 14:45:27			
Apogee	1/21/2018 13:20:34	Maneuver Window Start	1/21/2018 13:22:58	Maneuver Window End	1/21/2018 13:53:00		
Apogee Target	targetX:0.5183419486075703 targetY:-0.7845079392379991  targetZ:-0.3403952373142942,						
15 R <sub>E</sub> desc. Date/Time	1/16/2018 14	:55:12	14 R <sub>E</sub> desc. Date/Time	1/16/2018 16:20:09			
Perigee	1/26/2018 00:22:11	Maneuver Window Start	1/25/2018 14:27:22	Maneuver Window Stop	1/26/2018 10:52:43		
Perigee Target	targetX:0.53857400000000000 targetY:-0.76922100000000004  targetZ:-0.34385599999999999						
Eclipse	Yes	Eclipse Start	1/26/2018 01:27:14	Eclipse End	1/26/2018 02:29:53		
Sun Mnvr	Yes	Apogee/Perigee	Apogee	Sun Angle at DESCENDING			
Approved Version	IBEX_2018_017_o0394a_v001.scr						

Activity	Command Checks	Date Done	Done By
Supporting Materials	<ol> <li>IBEX_CrossingTimes_<date>_v00x.txt on SFTP at /IBEX/fdg/PredictedEphemeris/Orbit Events/.</date></li> <li>Orbit Events File on SFTP at /IBEX/moc/Moc-Soc/oef/.</li> <li>Command Constraint Violations Report on SFTP at /IBEX/moc/Moc-Soc/cvr/.</li> <li>Contacts this orbit Orbit_oXXX.txt included in the ATS approval email.</li> <li>Science Tasking File at /IBEX/moc/Soc-Moc/stf/.</li> <li>Merged ATS at <a href="http://ibex.unh.edu/cgi-bin/ats.cgi">http://ibex.unh.edu/cgi-bin/ats.cgi</a>.</li> </ol>	01/07/18	NGA
Sun Maneuvers	<ul> <li>Additional contacts should not be planned to support IBEX Sun Precession Maneuvers due to star tracker outages. The standard apogee and perigee contacts should be used to verify that a maneuver has occurred. If it is not possible to plan one of the standard contacts after the star tracker outage is down to 50% and a valid quaternion reading can be made to verify the maneuver, the coarse Sun sensor angle and the thruster pulse count will be used to determine a) whether a maneuver took place, and b) whether the pointing after the maneuver is as expected +/- 2 degrees.</li> </ul>	01/07/18	NGA
	The nominal off-Sun pointing constraint is 7.25 degrees. Based on the missed maneuver in orbit 114, the payload team has determined that there is no hardware risk associated with off-Sun pointing up to angles of at least 13 degrees. There is a higher background noted in the data starting at around 9.5 degrees off Sun pointing.		
File Input Check	<ol> <li>Current OEF inputs are Forecast STF, last orbit's OEF &amp; latest ephemeris.</li> <li>ATS inputs are this orbit's OEF &amp; STF. (And ABS if present.)</li> <li>ATS filename is of the format IBEX_yyyy_doy_o0xxxa_v0zz.scr.         where IBEX is capitalized, yyyy is the year, doy is the day of year, xxx is the 3-digit orbit number and zz is the 2-digit version number.         Any special operations ATSs will have another designation between the orbit number and version number (i.e. *o0186a hgc v001 for the Hi gain curve).</li> </ol>	01/07/18	NGA

Falinaga	1.	Check OEF for eclipses during the orbit.	04/07/49	NCA
Eclipses	3.	Verify long eclipse flag start & stop times reflect Ryan Tyler's recommendations based on his eclipse diagnostic tool. Suggestions made by Ryan after the use of this tool trump the general guidelines below. (Please note, specific timing may shift if the recommendations are relative to eclipse timing. For example, it may say set LE flag to false X hours after the end of the eclipse with a given FALSE time suggested. If the eclipse timing changes as the ephemeris becomes more refined, this command time may shift.)  Verify no contacts planned during an eclipse. Note: If in conflict, the eclipse diagnostic recommendations will trump the general guidelines below.  a Verify transmitter OFF from 30 minutes before eclipse start through the end of the eclipse.  b For an eclipse where the long eclipse flag is set, schedule a SOH contact directly following the end of the eclipse (or per Ryan's assessment).  c Set the LE flag according to Ryan's assessments.  Verify no maneuver planned during an eclipse. Note: If in conflict, the eclipse diagnostic recommendations will trump the general guidelines below.  a Verify no maneuver or cat bed heaters on from 3 hours before eclipse start through 3 hours after eclipse end.  b Verify no maneuver or cat bed heaters are on while the long eclipse flag is set.  Verify the following additional constraints (from battery balancing section).  a Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to FALSE.  b Verify P/L is in HVSTANDBY or HVENG.  c Verify no charging cycle within 2 hours of ASCENDING or DESCENDING macro execution.	01/07/18	NGA
		This applies to all eclipses, not just moderate or long eclipses.		_
Moon In Lo FOV	<ol> <li>3.</li> <li>4.</li> </ol>	<ul> <li>MoonInLoFovStart 1/20/2018 04:55:18</li> <li>MoonInLoFovStop 1/21/2018 04:06:30</li> <li>MoonInLoFovStart 1/21/2018 13:32:49 - short: no commands in ATS</li> <li>MoonInLoFovStop 1/21/2018 17:26:44</li> <li>Check for corresponding Moon in Lo FOV start commands in ATS (timing will not be exact).</li> <li>PMT_LVL 300 \$TIME=2018/01:20:12:51:23</li> <li>IF_STAR_ADJ 0 \$TIME=2018/01:20:12:51:25</li> <li>Note: if the Moon is closer than 30Re, the PMT will be set to 250. The distance to the moon can be found in the STF.</li> <li>Check for corresponding Moon in Lo FOV stop commands.</li> <li>IF_STAR_ADJ 250 \$TIME=2018/01:21:09:12:07</li> <li>PMT_LVL 800 \$TIME=2018/01:21:09:12:09</li> <li>Note: if the Moon is still in the FOV at the time of DESCENDING, no Moon in Lo FOV stop commands will be present in ATS. The values are reset to the default at next set of ASCENDING macros.</li> <li>If Moon in Lo FOV starts in arc a &amp; ends in arc b, check Moon in Lo FOV Start commands resent</li> </ul>	01/07/18	NGA
	5.	after apogee ASCENDING commands.  If Moon in Lo FOV starts within apogee HVSTANDBY period, check Moon in Lo FOV Start commands sent after apogee ASCENDING commands.		

0 1 1		0.4/03	7/40
Contact Commands	. Each contact has 5 co		7/18 NGA
Commands	=	es, downlink rate against <i>Orbit_oXXX.txt</i> file.	
	=	previous ATS have not been duplicated.	
		anned contacts in Orbit_xxx.txt are in the ATS.	
		ontains the following 5 commands.	
	<ul> <li>SetRelay stx,on</li> </ul>		
		(2K, 40K, 64K, 160K, or 320K)	
		utControlReg STXMODE_Strobe,ON	
		utControlReg COHERENT,ON	
	SetRelay stx,off		
	. If contact is near an ecl		
		litter OFF from 30 minutes before eclipse start through 30 minutes after eclipse	
	end.	ransmitter constraints exist they will be contured in Byan's recommendations	
		ransmitter constraints exist, they will be captured in Ryan's recommendations.  ng used for an SSR Dump, the data rate should be at least 160 ksps & the SSR	
		should be included in the contact commands. Commands in Orange should only	
		ers need to be reset this perigee. These commands should be separated by 2s and	
		DUMP_NEW command.	
	SetRelay stx,on	_	
	SetDownlink2K		
		utControlReg STXMODE_Strobe,ON	
		utControlReg COHERENT,ON	
	SetDownlink32		
	<ul> <li>SSR_DUMP_NE</li> </ul>		
	SSR_SET_RD_P		
	• SSR_SET_WRT_		
	<ul> <li>SetRelay stx,off</li> </ul>		
SC State	. Transition to Science	state will be first command of each ATS (at 14 Re).	7/18 NGA
Science:	<ul> <li>SetScState scien</li> </ul>	nce \$TIME=2018/01:17:13:24:48	
arc a		be the next command (at 14 Re).	
	• LO_SCIENCE_		
		Science again at the end of the ATS. The ATS commands go from 14 Re	
	to 14 Re in each orbit		
		o Science commands for this orbit are not part of the previous ATS using	
	<ul><li><a href="http://ibex.unh.edu/">http://ibex.unh.edu/</a></li><li><a href="http://ibex.unh.edu/">Verify that the beginn</a></li></ul>		
		ing of this ATS does not overlap with the end of the previous orbit's ATS n.edu/cgi-bin/ats.cgi.	
		mes report that it occurs about 15Re ascending. The arc a ASCENDING	
Payload		any time at or above 15Re ascending.	7/18 NGA
Mode	<ol> <li>Verify commanding to</li> </ol>		
HVSCI:	<ul> <li>ASCENDING_PL</li> </ul>	1 \$TIME=2018/01:17:15:01:06	
arc a	<ul><li>ASCENDING_HI</li></ul>		
	SET_PARAMETE	ER 1, TLM_RATE_SOH	
	<ul> <li>SET_PARAMETE</li> </ul>	ER 4, HV_STEP_DWELL	
	<ul><li>SET_PARAMETE</li></ul>	ER 3, HV_STEP_FRAC	
	<ul> <li>HI_COL_NEG_L\</li> </ul>	VL 1400	
	• CEU_HI_CEM_1	_LVL 1780	
	<ul><li>CEU_HI_CEM_2</li></ul>	LLVL 1780	
	<ul><li>CEU_HI_CEM_3</li></ul>	3_LVL 1780	
	<ul><li>CEU_HI_CEM_4</li></ul>		
	<ul><li>SET_PARAMETE</li></ul>	ER O, TLM_RATE_SOH	
	<ul> <li>ASCENDING_PL</li> </ul>	2	
	<ul><li>ASCENDING_PL</li></ul>	1	
	<ul> <li>ASCENDING_LO</li> </ul>		
1	<ul> <li>ASCENDING PI</li> </ul>	2 \$TIME=2018/01:17:15:13:36	

Payload Mode HVSTANDBY : arc a	<ol> <li>Payload DESCENDING commands end 1.5h before thruster enable.</li> <li>DESCENDING_PL1 \$TIME=2018/01:21:11:27:00</li> <li>DESCENDING_LO</li> <li>ASCENDING_PL2</li> <li>DESCENDING_PL1</li> <li>DESCENDING_HI</li> <li>DESCENDING_PL2 \$TIME=2018/01:21:11:49:50</li> </ol>	01/07/18	NGA
SC State HK : arc a	<ol> <li>Spacecraft Housekeeping command occurs 1h before thruster enable.</li> <li>SetScState housekeeping \$TIME=2018/01:21:12:23:00</li> </ol>	01/07/18	NGA
Inertial Maneuver : Apogee	1. Use this command sequence if an apogee inertial maneuver is used, otherwise skip to the 'Sun Precession Maneuver : Apogee' sequence below.  2. Verify Thruster enable command occurs within STF maneuver window.  3. Verify no eclipse occurs from cat bed heater on through set FC mode Mission.  4. Verify cat bed heaters come on 55 min before burn.  • CATBED_5N_HTR,ON  5. Verify Kalman Filter input select is ground command & estimator update is disabled.  • SetKFInputSelect GND_CMD, 0, 0, 0, 0  • SetEstUpdateEnables ENABLE, DISABLE  6. Verify in FC mode Burn.  • SetIrcMode burn  7. Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match.  • SetInrDir  • targetX targetY   • targetZ  8. Verify inertial maneuver chosen.  • SetLrTarget ACS_INERTIAL  9. Verify thrust time set to 11 min.  • SetThrustTime 660  10. Verify thruster enable command matches RepointingManeuverStart time in OEF.  • SetThrustEnable ENABLE  • RepointingManeuverStart  11. Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0.  • SetThrustEnable DISABLE  • SetThrustEnable DISABLE  • SetThrustEnable DISABLE  • SetThrustTime 0  12. Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission.  • SetStaticZrate ESTIMATOR, 0.418  • SetKFInputSelect STA_PCT_VALID, 43,28,33,48	N/A	
	<ul><li>SetKFInputSelect STA_PCT_VALID, 43,28,33,48</li><li>SetFcMode Mission</li></ul>		

0	1.	Use this command sequence in the event of an apogee Sun maneuver.	04/07/40	NOA
Sun	2.	Verify Thruster enable command occurs within STF maneuver window.	01/07/18	NGA
Precession Maneuver		Verify no eclipse occurs from cat bed heater on through set FC mode Mission.		
		Verify cat bed heaters powered on 55 min before thruster enable.		
: Apogee		• CATBED_5N_HTR,ON \$TIME=2018/01:21:12:27:58		
	5.	Verify in FC mode Burn and Sun target.		
		SetFcMode burn		
		SetLrTarget ACS_SUN		
	6.	Verify thrust time set to 16 min.		
	٥.	SetThrustTime 960		
	7.	Verify thruster enable command matches SunMvrBegin time in OEF.		
		SetThrustEnable ENABLE \$TIME=2018/01:21:13:22:58		
		SunMvrBegin 2018-01-21T13:22:58		
	8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set		
	0.	to 0, FC mode Mission.		
		SetThrustEnable DISABLE \$TIME=2018/01:21:13:37:58		
		SetHTRCmd CATBED_5N_HTR,OFF  SetTheoretTime 0.		
		SetThrustTime 0		
		SetFcMode Mission		
SC State	1.	Spacecraft Science commands occur ~1h after thruster Disable.	01/07/18	NGA
Science :		• SetScState science \$TIME=2018/01:21:14:38:04		
arc b		LO_SCIENCE_MODE NORMAL		
	1.	Verify payload ASCENDING commands begin at least 1.5 hours after thruster DISABLE.	04/07/40	NOA
Payload	2.	Verify commands take ~24 minutes to execute.	01/07/18	NGA
Mode		• ASCENDING_PL1 \$TIME=2018/01:21:15:08:04		
HVSCI:		ASCENDING_HI		
arc b		SET_PARAMETER 1, TLM_RATE_SOH		
		SET_PARAMETER 4, HV_STEP_DWELL		
		SET_PARAMETER 3, HV_STEP_FRAC		
		• HI_COL_NEG_LVL 1400		
		• CEU_HI_CEM_1_LVL 1780		
		• CEU_HI_CEM_2_LVL 1780		
		CEU_HI_CEM_3_LVL 1780  CEV_HI_CEM_3_LVL 1780		
		CEU_HI_CEM_4_LVL 1900		
		SET_PARAMETER 0, TLM_RATE_SOH		
		ASCENDING_PL2		
		ASCENDING_PL1		
		ASCENDING_LO		
		• ASCENDING_PL2 \$TIME=2018/01:21:15:31:52		
Payload	1.	Verify w/ Crossing Times report that it occurs about 15 Re descending. The arc b DESCENDING	01/07/19	NCA
Mode		commands can complete any time at or above 15Re descending.	01/07/18	NGA
HVSTANDBY	2.	Verify commands take ~23 minutes to execute.		
: arc b		• DESCENDING_PL1 \$TIME=2018/01:25:12:06:37		
		DESCENDING_LO		
		ASCENDING_PL2		
		• DESCENDING_PL1		
		DESCENDING_HI		
		• DESCENDING_PL2 \$TIME=2018/01:25:12:18:28		
SC State HK	1.	Verify with Crossing Times report that Transition to Housekeeping state occurs at 14 Re desc (or	01/07/18	NGA
: arc b		an hour before the maneuver if the maneuver occurs less than 1 hour after 14 Re desc).		
	1	<ul> <li>SetScState housekeeping \$TIME=2018/01:25:13:29:51</li> </ul>		

meruai	1.	Tise has command segmence if a neddee inemal maneriver is lised, otherwise skin to the "Slin		
		Use this command sequence if a perigee inertial maneuver is used, otherwise skip to the 'Sun	01/07/18	NGA
Maneuver:	2.	Precession Maneuver: Perigee' sequence below.  Verify no eclipse occurs from cat bed heater on through set FC mode Mission.		
		Verify no eclipse occurs from car bed heater on though set i c mode wission.  Verify cat bed heaters come on 55 min before burn.		
	Ο.	CATBED_5N_HTR,ON \$TIME=2018/01:25:13:32:22		
/	4.	Verify in Housekeeping state.		
		Verify Kalman Filter input select is ground command & estimator update is disabled.		
	Ο.	SetKFInputSelect GND_CMD, 0, 0, 0, 0		
		SetEstUpdateEnables ENABLE, DISABLE		
	6.	Verify in FC mode Burn.		
	0.	SetFcMode burn		
7	7.	Compare SetInrDir in ATS with target vector in the Forecast STF & verify the vectors match.		
'	٠.	SetInrDir 17.73 with target vector in the Forecast OTF & verify the vectors match.      SetInrDir 0.538574,-0.769221,-0.343856		
		targetX:0.538574000000000000 targetY:-0.7692210000000004		
		targetZ:-0.3438559999999999		
ء ا	8.	Verify inertial maneuver chosen.		
	Ο.	SetLrTarget ACS_INERTIAL		
c	9.	Verify thrust time set to 11 min.		
	٥.	SetThrustTime 660		
1	10	Verify thruster enable command matches RepointingManeuverStart time in OEF.		
	10.	SetThrustEnable ENABLE \$TIME=2018/01:25:14:27:22		
		RepointingManeuverStart 2018-01-25T14:27:22		
1	11	Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set		
	٠	to 0.		
		SetThrustEnable DISABLE \$TIME=2018/01:25:14:37:22		
		• CATBED_5N_HTR,OFF		
		SetThrustTime 0		
1	12.	Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission.		
		SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/01:25:14:52:32		
		<ul> <li>SetKFInputSelect STA_PCT_VALID, 43,28,33,48</li> </ul>		
		SetFcMode Mission		
_ 1	1.	Use this command sequence in the event of a perigee Sun maneuver.	21/2	
Suii		Verify Thruster enable command occurs within STF maneuver window.	N/A	
r recession 2		Verify no eclipse occurs from cat bed heater on through set FC Mode Mission.		
		Verify cat bed heaters come on 55 min before burn.		
rengee		• CATBED_5N_HTR,ON		
5	5.	Verify in FC mode Burn and Sun target.		
		SetFcMode burn		
		SetLrTarget ACS_SUN		
6	6.	Verify thrust time set to 16 min.		
		SetThrustTime 960		
7	7.	Verify thruster enable command matches SunMvrBegin time in OEF.		
		SetThrustEnable ENABLE		
		SunMvrBegin		
8	8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set		
		to 0, FC mode Mission.		
		SetThrustEnable DISABLE		
		SetHTRCmd CATBED_5N_HTR,OFF		
		SetThrustTime 0		
		SetFcMode Mission		

## IBEX Command Approval Checklist C. Reno

Rev 16b Last update 06/08/2016

Battery Cell Balancing	1. 2. 3. 4. 5. 6. 7.	There will be battery cell balancing every 2 out of 3 orbits. Battery cell balancing this orbit? N Verify charging cycle (Long eclipse flag=TRUE) is 90 minutes long. Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to FALSE. Verify P/L is in HVSTANDBY or HVENG. Verify no charging cycle within 2 hours of ASCENDING or DESCENDING macro execution. Verify no charging cycle within 1 hour of maneuver. Verify no charging cycle during an eclipse.	01/07/18 Eclipse flag set for short eclipse	NGA
Cmd Violation	1.	Review CCVR. If you have any questions Reply All to the ATS Approval email and ask the team.	01/07/18	NGA

	Anomaly Response : Non-nominal burn	Date Completed	Completed By
•	If the maneuver has not occurred or the spacecraft pointing as designated by either the star tracker or coarse Sun sensor is off by more than 2 degrees from the expected pointing, an anomaly has occurred.	•	
	<ul> <li>If the spacecraft is in Contingency state all stored commands are flushed from the command queue. Follow standard anomaly process.</li> </ul>		
	<ul> <li>If the Sun maneuver did not occur and the spacecraft is in either Science or Housekeeping state follow the steps below.</li> </ul>		
	Housekeeping state follow the steps below.		
•	12.5 degree constraint; this constraint is in place because we should not exceed the largest		
	If the payload is in HVSTANDBY, LVENG or OFF, and there are no commands loaded to bring it to HVSCI voltages, no operational pointing constraints will be		
	violated. Follow standard anomaly process.  • If the payload in HVSCI mode or there are uploaded commands to bring the		
	a. Determine current off Sun pointing. If the off Sun angle has already exceeded 12.5		
	DESCENDING command suite in real-time, as described below. If this cannot be		
	will be planned as soon as possible to execute these commands.  @CEU_MACRO_EXEC DESCENDING_PL1 (< 1 min)		
	<pre>@CEU_MACRO_EXEC DESCENDING_HI (~ 8 min) @CEU_MACRO_EXEC DESCENDING_PL2 (&lt; 1 min)</pre>		
	perigee Sun precession maneuver is completely missed after an inertial apogee		
	b. If current Sun pointing is below 12.5 degrees, the ISOC should input ST Sunpointing angle into ibex_rotate to determine the Sun angle at the time of		
	Sun-Angle at payload DESCENDING		
	action is needed for this arc. Follow standard anomaly response process.		
	should be sent.		
	commands executing early such that 12.5 degrees is not exceeded while the payload is in HVSCI.		
	ii. The MOC will create an associated ATS. iii.Approval is needed by the MOM, MOC & ISOC prior to upload.		
	to upload the commands prior to exceeding the 12.5 degree constraint.		
		If the maneuver has not occurred or the spacecraft pointing as designated by either the star tracker or coarse Sun sensor is off by more than 2 degrees from the expected pointing, an anomaly has occurred.  If the spacecraft is in Contingency state all stored commands are flushed from the command queue. Follow standard anomaly process.  If the Sun maneuver did not occur and the spacecraft is in either Science or Housekeeping state follow the steps below.  If a partial Sun maneuver has occurred and the spacecraft is in either Science or Housekeeping state follow the steps below.  Please note that there is no anticipated hardware damage associated with exceeding the 12.5 degree constraint; this constraint is in place because we should not exceed the largest pointing achieved thus far in the mission.  If the payload is in HVSTANDBY, LVENG or OFF, and there are no commands loaded to bring it to HVSCI voltages, no operational pointing constraints will be violated. Follow standard anomaly process.  If the payload in HVSCI mode or there are uploaded commands to bring the payload to HVSCI mode or there are uploaded commands to bring the payload to HVSCI mode,  Determine current off Sun pointing. If the off Sun angle has already exceeded 12.5 degrees, the MOC should notify the MOM and immediately send the DESCENDING command suite in real-time, as described below. If this cannot be done in the contact where the pointing anomaly was discovered, another contact will be planned as soon as possible to execute these commands.  @CEU_MACRO_EXEC_DESCENDING_HI (<1 min)  @CEU_MACRO_EXEC_DESCENDING_LO (~10 min)  @CEU_MACRO_EXEC_DESCENDING_LO (~10 min)  @CEU_MACRO_EXEC_DESCENDING_LO (~10 min)  @CEU_MACRO_EXEC_DESCENDING_LO (~10 min)  @CEU_MACRO_EXEC_DESCENDING_LO, (>10 min)  Please note: The only scenario where hitting 12.5 degrees is expected is when a perigee Sun precession maneuver is completely missed after an inertial apogee maneuver which occurs late in the maneuver window (near apogee + 10 hours).  If current Sun pointing is	■ If the maneuver has not occurred or the spacecraft pointing as designated by either the star tracker or coarse Sun sensor is off by more than 2 degrees from the expected pointing, an anomaly has occurred.  ■ If the spacecraft is in Contingency state all stored commands are flushed from the command queue. Follow standard anomaly process.  ■ If the Sun maneuver did not occur and the spacecraft is in either Science or Housekeeping state follow the steps below.  ■ If a partial Sun maneuver has occurred and the spacecraft is in either Science or Housekeeping state follow the steps below.  ■ Please note that there is no anticipated hardware damage associated with exceeding the 12.5 degree constraint; this constraint is in place because we should not exceed the largest pointing achieved thus far in the mission.  ■ If the payload is in HVSTANDBY, LVENG or OFF, and there are no commands loaded to bring it to HVSCI voltages, no operational pointing constraints will be violated. Follow standard anomaly process.  ■ If the payload in HVSCI mode or there are uploaded commands to bring the payload to HVSCI mode,  a. Determine current off Sun pointing. If the off Sun angle has already exceeded 12.5 degrees, the MOC should notify the MOM and immediately send the DESCENDING command suite in real-time, as described below. If this cannot be done in the contact where the pointing anomaly was discovered, another contact will be planned as soon as possible to execute these commands.  ②CEU_MACRO_EXEC DESCENDING_PL1 (<1 min) ②CEU_MACRO_EXEC DESCENDING_PL2 (<1 min) Please note: The only scenario where hitting 12.5 degrees is expected is when a perigee Sun precession maneuver is completely missed after an inertial apogee maneuver which occurs late in the maneuver window (near apogee + 10 hours).  b. If current Sun pointing is below 12.5 degrees, the ISOC should input ST Sunpointing angle into ibex_rotate to determine the Sun angle at the time of DESCENDING.  Sun-Angle at payload DESCENDING.  c. If 12.5 degrees is not exceeded by the t