IBEX Command Approval Checklist Rev 16b incorporates post-ST anomaly changes and resetting the SSR pointers in an APL contact.

Orbit	398	Special Ops	ISN Pointing			
14 R _E asc. Date/Time	2/22/2018 07	:22:44	15 R _E asc. Date/Time	5 R _E asc. Date/Time 2/22/2018 08:55:50		
Apogee	2/26/2018 09:32:12	Maneuver Window Start	2/25/2018 23:28:46	Maneuver Window End	2/26/2018 19:28:48	
Apogee Target						
15 R _E desc. Date/Time	3/2/2018 10:4	10:44:05 14 R _E desc. Date/Time 3/2/2018 12:17:48				
Perigee	3/2/2018 22:31:03	Maneuver Window Start	3/2/2018 12:44:45	Maneuver Window End	3/3/2018 08:39:36	
Perigee Target	<pre>targetX:0.9571 targetZ:-0.124</pre>		0 targetY:-0.2613	33800000000001		
Eclipse	No	Eclipse Start		Eclipse End		
Sun Mnvr	No	Apogee/Perigee		Sun Angle at DESCENDING		
Approved Version	IBEX_2018_052	_00398a_v001.s	cr			

Activity	Command Checks	Date Done	Done By
Supporting Materials	 IBEX_CrossingTimes_<date>_v00x.txt on SFTP at /IBEX/fdg/PredictedEphemeris/Orbit Events/.</date> Orbit Events File on SFTP at /IBEX/moc/Moc-Soc/oef/. Command Constraint Violations Report on SFTP at /IBEX/moc/Moc-Soc/cvr/. Contacts this orbit Orbit_oXXX.txt included in the ATS approval email. Science Tasking File at /IBEX/moc/Soc-Moc/stf/. Merged ATS at http://ibex.unh.edu/cgi-bin/ats.cgi. 		
Sun Maneuvers	 Additional contacts <i>should not</i> be planned to support IBEX Sun Precession Maneuvers due to star tracker outages. The standard apogee and perigee contacts should be used to verify that a maneuver has occurred. If it is not possible to plan one of the standard contacts after the star tracker outage is down to 50% and a valid quaternion reading can be made to verify the maneuver, the coarse Sun sensor angle and the thruster pulse count will be used to determine a) whether a maneuver took place, and b) whether the pointing after the maneuver is as expected +/- 2 degrees. The nominal off-Sun pointing constraint is 7.25 degrees. Based on the missed maneuver in orbit 114, the payload team has determined that there is no hardware risk associated with off-Sun pointing up to angles of at least 13 degrees. There is a higher background noted in the data starting at around 9.5 degrees off Sun pointing. 	N/A	NGA
File Input Check	 Current OEF inputs are Forecast STF, last orbit's OEF & latest ephemeris. ATS inputs are this orbit's OEF & STF. (And ABS if present.) ATS filename is of the format IBEX_yyyy_doy_00xxxa_v0zz.scr. where IBEX is capitalized, yyyy is the year, doy is the day of year, xxx is the 3-digit orbit number and zz is the 2-digit version number. Any special operations ATSs will have another designation between the orbit number and version number (i.e. *00186a hgc v001 for the Hi gain curve). 	02/15/18	NGA

		T	
Eclipses	 Check OEF for eclipses during the orbit. Verify long eclipse flag start & stop times reflect Ryan Tyler's recommendations based on his eclipse diagnostic tool. Suggestions made by Ryan after the use of this tool trump the general guidelines below. (Please note, specific timing may shift if the recommendations are relative to eclipse timing. For example, it may say set LE flag to false X hours after the end of the eclipse with a given FALSE time suggested. If the eclipse timing changes as the ephemeris becomes more refined, this command time may shift.) Verify no contacts planned during an eclipse. Note: If in conflict, the eclipse diagnostic recommendations will trump the general guidelines below. a Verify transmitter OFF from 30 minutes before eclipse start through the end of the eclipse. b For an eclipse where the long eclipse flag is set, schedule a SOH contact directly following the end of the eclipse (or per Ryan's assessment). c Set the LE flag according to Ryan's assessments. Verify no maneuver planned during an eclipse. Note: If in conflict, the eclipse diagnostic recommendations will trump the general guidelines below. a Verify no maneuver or cat bed heaters on from 3 hours before eclipse start through 3 hours after eclipse end. b Verify no maneuver or cat bed heaters are on while the long eclipse flag is set. Verify the following additional constraints (from battery balancing section). a Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to FALSE. b Verify P/L is in HVSTANDBY or HVENG. c Verify no charging cycle within 2 hours of ASCENDING or DESCENDING macro execution. This applies to all eclipses, not just moderate or lon	N/A	NGA
Moon In Lo FOV	 Check OEF for Moon in Lo FOV events. MoonInLoFovStart 2/22/2018 21:13:41 MoonInLoFovStop 2/23/2018 16:55:26 Check for corresponding Moon in Lo FOV start commands in ATS (timing will not be exact). PMT_LVL 300 \$TIME=2018/02:22:23:11:38 IF_STAR_ADJ 0 \$TIME=2018/02:22:23:11:40 Note: if the Moon is closer than 30Re, the PMT will be set to 250. The distance to the moon can be found in the STF. Check for corresponding Moon in Lo FOV stop commands. IF_STAR_ADJ 250 \$TIME=2018/02:23:15:16:10 PMT_LVL 800 \$TIME=2018/02:23:15:16:12 Note: if the Moon is still in the FOV at the time of DESCENDING, no Moon in Lo FOV stop commands will be present in ATS. The values are reset to the default at next set of ASCENDING macros. If Moon in Lo FOV starts in arc a & ends in arc b, check Moon in Lo FOV Start commands resent after apogee ASCENDING commands. If Moon in Lo FOV starts within apogee HVSTANDBY period, check Moon in Lo FOV Start commands sent after apogee ASCENDING commands. 	02/15/18	NGA

Cantaat	1 Fach contact has 5 commands	02/15/19	NCA
Contact Commands	 Each contact has 5 commands. Varify STX on off times, downlink rate against Orbit, sXXX tot file. 	02/15/18	NGA
Commanus	1. Verify STX on/off times, downlink rate against <i>Orbit_oXXX.txt</i> file.		
	2. Verify contacts in the previous ATS have not been duplicated.		
	Verify all currently planned contacts in Orbit_xxx.txt are in the ATS.		
	Verify each contact contains the following 5 commands.		
	SetRelay stx,on		
	 SetDownlink2K (2K, 40K, 64K, 160K, or 320K) 		
	 SetBilevelOutputControlReg STXMODE_Strobe,ON 		
	SetBilevelOutputControlReg COHERENT,ON		
	SetRelay stx,off		
	5. If contact is near an eclipse		
	a. Verify transmitter OFF from 30 minutes before eclipse start through 30 minutes after eclipse		
	end.		
	b. If additional transmitter constraints exist, they will be captured in Ryan's recommendations.		
	6. If an APL contact is being used for an SSR Dump, the data rate should be at least 160 ksps & the SSR		
	DUMP_NEW command should be included in the contact commands. Commands in Orange should only		
	be sent if the SSR pointers need to be reset this perigee. These commands should be separated by 2s and		
	occur 2s after the SSR_DUMP_NEW command.		
	SetRelay stx,on		
	• SetDownlink2K		
	SetBilevelOutputControlReg STXMODE_Strobe,ON		
	SetBilevelOutputControlReg COHERENT,ON		
	• SetDownlink320K		
	• SSR_DUMP_NEW		
	• SSR_SET_RD_PTR 6500		
	SSR_SET_WRT_PTR 6500		
	SetRelay stx,off		
SC State	1. Transition to Science state will be first command of each ATS (at 14 Re).	02/15/18	NGA
Science: arc	 SetScState science \$TIME=2018/02:22:07:23:23 		
а	2. Lo science mode will be the next command (at 14 Re).		
	• LO SCIENCE MODE NORMAL		
	3. Verify no transition to Science again at the end of the ATS. The ATS commands go from 14 Re to 14 Re		
	in each orbit.		
	4. Verify the transition to Science commands for this orbit are not part of the previous ATS using		
	http://ibex.unh.edu/cgi-bin/ats.cgi.		
	5. Verify that the beginning of this ATS does not overlap with the end of the previous orbit's ATS using		
	http://ibex.unh.edu/cgi-bin/ats.cgi.		
D 1 1	1. Verify w/ Crossing Times report that it occurs about 15Re ascending. The arc a ASCENDING commands	00/15/10	NGA
Payload	can start any time at or above 15Re ascending.	02/15/18	NGA
	can start any time at of above 15 ke ascending.		
Mode	 Verify commanding takes ~ 24 minutes. 		
Mode HVSCI :			
Mode	2. Verify commanding takes ~ 24 minutes.		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL SET_PARAMETER 3, HV_STEP_FRAC 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL SET_PARAMETER 3, HV_STEP_FRAC HI_COL_NEG_LVL 1400 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL SET_PARAMETER 3, HV_STEP_FRAC HI_COL_NEG_LVL 1400 CEU_HI_CEM_1_LVL 1780 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL SET_PARAMETER 3, HV_STEP_FRAC HI_COL_NEG_LVL 1400 CEU_HI_CEM_1_LVL 1780 CEU_HI_CEM_2_LVL 1780 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL SET_PARAMETER 3, HV_STEP_FRAC HI_COL_NEG_LVL 1400 CEU_HI_CEM_1_LVL 1780 CEU_HI_CEM_2_LVL 1780 CEU_HI_CEM_3_LVL 1780 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL SET_PARAMETER 3, HV_STEP_FRAC HI_COL_NEG_LVL 1400 CEU_HI_CEM_1_LVL 1780 CEU_HI_CEM_2_LVL 1780 CEU_HI_CEM_3_LVL 1780 CEU_HI_CEM_4_LVL 1900 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL SET_PARAMETER 3, HV_STEP_FRAC HI_COL_NEG_LVL 1400 CEU_HI_CEM_1_LVL 1780 CEU_HI_CEM_3_LVL 1780 CEU_HI_CEM_4_LVL 1900 SET_PARAMETER 0, TLM_RATE_SOH 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL SET_PARAMETER 3, HV_STEP_FRAC HI_COL_NEG_LVL 1400 CEU_HI_CEM_1_LVL 1780 CEU_HI_CEM_2_LVL 1780 CEU_HI_CEM_3_LVL 1780 CEU_HI_CEM_4_LVL 1900 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL SET_PARAMETER 3, HV_STEP_FRAC HI_COL_NEG_LVL 1400 CEU_HI_CEM_1_LVL 1780 CEU_HI_CEM_3_LVL 1780 CEU_HI_CEM_4_LVL 1900 SET_PARAMETER 0, TLM_RATE_SOH 		
Mode HVSCI :	 2. Verify commanding takes ~ 24 minutes. ASCENDING_PL1 \$TIME=2018/02:22:08:55:54 ASCENDING_HI SET_PARAMETER 1, TLM_RATE_SOH SET_PARAMETER 4, HV_STEP_DWELL SET_PARAMETER 3, HV_STEP_FRAC HI_COL_NEG_LVL 1400 CEU_HI_CEM_1_LVL 1780 CEU_HI_CEM_2_LVL 1780 CEU_HI_CEM_3_LVL 1780 CEU_HI_CEM_4_LVL 1900 SET_PARAMETER 0, TLM_RATE_SOH ASCENDING_PL2 		

Payload Mode		1. Payload DESCENDING commands end 1.5h before thruster enable.	02/15/18	NGA
HVSTANDBY		• DESCENDING_PL1 \$TIME=2018/02:25:21:32:48		
: arc a		DESCENDING_LO		
		ASCENDING_PL2		
		DESCENDING_PL1		
		DESCENDING_HI		
		 DESCENDING_PL2 \$TIME=2018/02:25:21:55:38 		
SC State HK :	1.	Spacecraft Housekeeping command occurs 1h before thruster enable.	02/15/18	NGA
arc a		SetScState housekeeping \$TIME=2018/02:25:22:28:48	02/10/10	non
Inertial	1.	Use this command sequence if an apogee inertial maneuver is used, otherwise skip to the 'Sun Precession	02/15/19	
Maneuver :		Maneuver : Apogee' sequence below.	02/15/18	NGA
Apogee	2.	Verify Thruster enable command occurs within STF maneuver window.		
npogee		Verify no eclipse occurs from cat bed heater on through set FC mode Mission.		
	4.	Verify cat bed heaters come on 55 min before burn.		
		 CATBED_5N_HTR,ON \$TIME=2018/02:25:22:33:46 		
	5.	Verify Kalman Filter input select is ground command & estimator update is disabled.		
		 SetKFInputSelect GND_CMD, 0, 0, 0, 0 		
		 SetEstUpdateEnables ENABLE, DISABLE 		
	6.	Verify in FC mode Burn.		
		SetFcMode burn		
	7.	Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match.		
		 SetInrDir 0.931355,-0.330158,-0.153538 		
		targetX:0.9313550000000004 targetY:-0.33015800000000001		
		targetZ:-0.1535380000000001		
	8.	Verify inertial maneuver chosen.		
		SetLrTarget ACS_INERTIAL		
	9.	Verify thrust time set to 11 min.		
		SetThrustTime 660		
	10.	Verify thruster enable command matches RepointingManeuverStart time in OEF.		
		 SetThrustEnable ENABLE \$TIME=2018/02:25:23:28:46 		
		RepointingManeuverStart 2018-02-25T23:28:46		
	11.	Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0.		
		SetThrustEnable DISABLE \$TIME=2018/02:25:23:38:46		
		 SetHTRCmd CATBED_5N_HTR,OFF 		
		SetThrustTime 0		
	12.	Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission.		
		 SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/02:25:23:53:56 		
		 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 		
		SetFcMode Mission		
	I	- Set emode mission	1	l

I	1			
11666991011	1. 2. 3. 4.	Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window. Verify no eclipse occurs from cat bed heater on through set FC mode Mission. Verify cat bed heaters powered on 55 min before thruster enable.	N/A	NGA
	5.	• CATBED_5N_HTR,ON Verify in FC mode Burn and Sun target.		
		SetFcMode burn		
	6	SetLrTarget ACS_SUN Varify thrust time set to 16 min		
	6.	 Verify thrust time set to 16 min. SetThrustTime 960 		
	7.	 Verify thruster enable command matches SunMvrBegin time in OEF. SetThrustEnable ENABLE 		
		SunMvrBegin		
	8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC mode Mission.		
		SetThrustEnable DISABLE		
		 SetHTRCmd CATBED_5N_HTR,OFF 		
		SetThrustTime 0		
		SetFcMode Mission		
SC State	1.	Spacecraft Science commands occur ~1h after thruster Disable.	02/15/18	NGA
Science : arc		 SetScState science \$TIME=2018/02:26:00:43:52 	02/15/18	NUA
b		LO_SCIENCE_MODE NORMAL		
D. 1. 1	1.	Verify payload ASCENDING commands begin at least 1.5 hours after thruster DISABLE.	02/15/18	NGA
Payload Mode	2.	Verify commands take ~24 minutes to execute.	02/13/18	NGA
HVSCI : arc		 ASCENDING_PL1 \$TIME= \$TIME=2018/02:26:01:13:52 		
b		ASCENDING_HI		
-		 SET_PARAMETER 1, TLM_RATE_SOH 		
		SET_PARAMETER 4, HV_STEP_DWELL		
		 SET_PARAMETER 3, HV_STEP_FRAC 		
		HI_COL_NEG_LVL 1400		
		 CEU_HI_CEM_1_LVL 1780 		
		 CEU_HI_CEM_2_LVL 1780 		
		 CEU_HI_CEM_3_LVL 1780 		
		 CEU_HI_CEM_4_LVL 1900 		
		 SET_PARAMETER 0, TLM_RATE_SOH 		
		ASCENDING_PL2		
		ASCENDING_PL1		
		ASCENDING_LO		
		 ASCENDING_PL2 \$TIME=2018/02:26:01:37:40 		
a yroad mode	1.	Verify w/ Crossing Times report that it occurs about 15 Re descending. The arc b DESCENDING	02/15/18	NGA
HVSTANDBY		commands can complete any time at or above 15Re descending.	02/10/10	NUA
: arc b	2.	Verify commands take ~23 minutes to execute.		
		 DESCENDING_PL1 \$TIME=2018/03:02:10:18:01 		
		DESCENDING_LO		
		ASCENDING_PL2		
		• DESCENDING_PL1		
		DESCENDING_HI		
		 DESCENDING_PL2 \$TIME=2018/03:02:10:40:51 		
SC State HK : arc b	1.	 Verify with Crossing Times report that Transition to Housekeeping state occurs at 14 Re desc (or an hour before the maneuver if the maneuver occurs less than 1 hour after 14 Re desc). SetScState housekeeping \$TIME=2018/03:02:11:48:33 	02/15/18	NGA

	1	Use this command sequence if a period inartial monouver is used, otherwise skin to the 'Sun Dracessian		
Inertial	1.	Use this command sequence if a perigee inertial maneuver is used, otherwise skip to the 'Sun Precession Maneuver : Perigee' sequence below.	02/15/18	NGA
Maneuver : Perigee	2.	Verify no eclipse occurs from cat bed heater on through set FC mode Mission.	Maneuver	
I engee	3.	Verify cat bed heaters come on 55 min before burn.	delayed due	
		• CATBED_5N_HTR,ON \$TIME=2018/03:02:19:31:45	to star	
	4.	Verify in Housekeeping state.	tracker	
	5.	Verify Kalman Filter input select is ground command & estimator update is disabled.	outage	
		SetKFInputSelect GND_CMD, 0, 0, 0, 0		
		SetEstUpdateEnables ENABLE, DISABLE		
	6.	Verify in FC mode Burn.		
	7	• SetFcMode burn		
	7.	 Compare SetInrDir in ATS with target vector in the Forecast STF & verify the vectors match. SetInrDir 0.957193,-0.261338,-0.124433 		
		targetX:0.95719299999999999996 targetY:-0.2613380000000001		
		targetZ:-0.124433000000000		
	8.	Verify inertial maneuver chosen.		
		SetLrTarget ACS_INERTIAL		
	9.	Verify thrust time set to 11 min.		
		SetThrustTime 660		
	10.	Verify thruster enable command matches RepointingManeuverStart time in OEF.		
		SetThrustEnable ENABLE \$TIME=2018/03:02:20:26:45		
		RepointingManeuverStart 2018-03-02T20:26:45		
	11.	Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0.		
		SetThrustEnable DISABLE \$TIME=2018/03:02:20:36:45		
		CATBED_5N_HTR,OFF		
		SetThrustTime 0		
	12.	Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission.		
		 SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/03:02:20:51:55 		
		 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 		
		SetFcMode Mission		
Sun	1.	Use this command sequence in the event of a perigee Sun maneuver.	N/A	NGA
Precession	2.	Verify Thruster enable command occurs within STF maneuver window.	10/11	11011
Maneuver :	3.	Verify no eclipse occurs from cat bed heater on through set FC Mode Mission.		
Perigee	4.	Verify cat bed heaters come on 55 min before burn.		
	~	• CATBED_5N_HTR,ON		
	5.	Verify in FC mode Burn and Sun target.		
		SetFcMode burn		
	6	SetLrTarget ACS_SUN		
	6.	Verify thrust time set to 16 min.		
	7.	 SetThrustTime 960 Verify thruster enable command matches SunMvrBegin time in OEF. 		
	1.	SetThrustEnable ENABLE		
		SunMvrBegin		
	8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC		
	0.	mode Mission.		
		SetThrustEnable DISABLE		
		SetHTRCmd CATBED_5N_HTR,OFF		
		SetThrustTime 0		
		SetFcMode Mission		
			00/15/10	NGA
D. H. C. II	4		02/15/18	NGA
Battery Cell	1.	There will be battery cell balancing every 2 out of 3 orbits. Battery cell balancing this orbit? N	02/13/10	
Battery Cell Balancing	2.	Verify charging cycle (Long eclipse flag=TRUE) is 90 minutes long.	02/13/10	
2		Verify charging cycle (Long eclipse flag=TRUE) is 90 minutes long. Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to	02/13/10	
5	2.	Verify charging cycle (Long eclipse flag=TRUE) is 90 minutes long. Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to FALSE.	02/13/10	
5	2.	Verify charging cycle (Long eclipse flag=TRUE) is 90 minutes long. Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to	02/13/10	
5	2. 3.	Verify charging cycle (Long eclipse flag=TRUE) is 90 minutes long. Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to FALSE.	02/13/18	
5	2. 3. 4.	Verify charging cycle (Long eclipse flag=TRUE) is 90 minutes long. Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to FALSE. Verify P/L is in HVSTANDBY or HVENG.	02/13/18	

IBEX Command Approval Checklist	
C. Reno	

Cmd 1. Review CCVR. If you have any questions Reply All to the ATS Approval email and ask the team. Violation	02/15/18	NGA	
---	----------	-----	--

Activity	Anomaly Response : Non-nominal burn	Date Completed	Completed By
	 If the maneuver has not occurred or the spacecraft pointing as designated by either the star tracker or coarse Sun sensor is off by more than 2 degrees from the expected pointing, an anomaly has occurred. If the spacecraft is in Contingency state all stored commands are flushed from the command queue. Follow standard anomaly process. If the Sun maneuver did not occur and the spacecraft is in either Science or Housekeeping state follow the steps below. If a partial Sun maneuver has occurred and the spacecraft is in either Science or Housekeeping state follow the steps below. Please note that there is no anticipated hardware damage associated with exceeding the 12.5 degree constraint; this constraint is in place because we should not exceed the largest pointing achieved thus far in the mission. 		
	 If the mission. If the payload is in HVSTANDBY, LVENG or OFF, and there are no commands loaded to bring it to HVSCI voltages, no operational pointing constraints will be violated. Follow standard anomaly process. If the payload in HVSCI mode or there are uploaded commands to bring the payload to HVSCI mode, a. Determine current off Sun pointing. If the off Sun angle has already exceeded 12.5 degrees, the MOC should notify the MOM and immediately send the DESCENDING command suite in real-time, as described below. If this cannot be done in the contact where the pointing anomaly was discovered, another contact will be planned as soon as possible to execute these commands. @CEU_MACRO_EXEC DESCENDING_LO (~10 min) @CEU_MACRO_EXEC DESCENDING_HI (~8 min) @CEU_MACRO_EXEC DESCENDING_HI (~8 min) @CEU_MACRO_EXEC DESCENDING_HI (~8 min) @CEU_MACRO_EXEC DESCENDING_PL1 (<1 min) @CEU_MACRO_EXEC DESCENDING_HI (~8 min) @CEU_MACRO_EXEC DESCENDING_HI (~8 min) @CEU_MACRO_EXEC DESCENDING_HI (~8 min) @CEU_MACRO_EXEC DESCENDING_HI (~1 min) @CEU_MACRO_EXEC DESCENDING_HI (~1 min) @CEU_MACRO_EXEC DESCENDING_HI (~1 min) @CEU_MACRO_EXEC DESCENDING_HI (~8 min) @CEU_MACRO_EXEC DESCENDING_HI (~1 min) @CEU_MACRO_EXEC DESCENDING_HI (~8 min) @CEU_MACRO_EXEC DESCENDING_HI (~1 min) @CEU_MACRO_EXEC DESCENDING_HI (~1 min) @CEU_MACRO_EXEC DESCENDING_HI (~8 min) @CEU_MACRO_EXEC DESCENDING_LI (~1 min) @CEU_MACRO_EXEC DESCENDING_HI (~8 min) @CEU_MACRO_EXEC DESCENDING_NI (~1 min) @		