IBEX Command Approval Checklist Rev 16d incorporates updated paths for the new SFTP server and general document clean up.

Orbit	411	Special Ops	o new 51 11 gerver and			
14 R _E asc. Date/Time	6/20/2018 10	:18:05	15 R _E asc. Date/Time	6/20/2018 12:06:36		
Apogee	6/24/2018 15:47:01	Maneuver Window Start	6/24/2018 05:52:33	Maneuver Window End	6/25/2018 01:52:35	
Apogee Target	targetX:-0.00942500000000000 targetY:0.921503999999999999 targetZ:0.38825599999999999					
15 R _E desc. Date/Time	16/28/2018 18:38:09		14 R _E desc. Date/Time	6/28/2018 20:20:54		
Perigee	6/29/2018 06:05:45	Maneuver Window Start	6/28/2018 20:56:59	Maneuver Window Stop	6/29/2018 15:56:51	
Perigee Target	targetX:-0.0870680000000001 targetY:0.91766099999999999 targetZ:0.3877090000000003					
Eclipse	No	Eclipse Start		Eclipse End		
Sun Mnvr	No	Apogee/Perigee		Sun Angle at DESCENDING		
Approved Version	IBEX_2018_171_	_o0411a_v001.s	cr			

Activity	Command Checks	Date Done	Done By
Supporting Materials	 IBEX_CrossingTimes_<date>_v00x.txt on SFTP at /Archive- Incoming/IBEXIncoming/FDG/PredictedEphemeris/Orbit Events/.</date> Orbit Events File on SFTP at /IBEXOutgoing/MOC/Moc-Soc/oef/. Command Constraint Violations Report on SFTP at /IBEXOutgoing/MOC/Moc-Soc/cvr/. Contacts this orbit Orbit_oXXX.txt included in the ATS approval email. Science Tasking File at /Archive-Incoming/IBEXIncoming/MOC/Soc-Moc/stf/. Merged ATS at http://ibex.unh.edu/cgi-bin/ats.cgi. 	06/09/18	NGA
Sun Maneuvers	 Additional contacts <i>should not</i> be planned to support IBEX Sun Precession Maneuvers due to star tracker outages. The standard apogee and perigee contacts should be used to verify that a maneuver has occurred. If it is not possible to plan one of the standard contacts after the star tracker outage is down to 50% and a valid quaternion reading can be made to verify the maneuver, the coarse Sun sensor angle and the thruster pulse count will be used to determine a) whether a maneuver took place, and b) whether the pointing after the maneuver is as expected +/- 2 degrees. The nominal off-Sun pointing constraint is 7.25 degrees. Based on the missed maneuver in orbit 114, the payload team has determined that there is no hardware risk associated with off-Sun pointing up to angles of at least 13 degrees. There is a higher background noted in the data starting at around 9.5 degrees off Sun pointing. 	N/A	
File Input Check	 Current OEF inputs are Forecast STF, last orbit's OEF & latest predictive ephemeris. ATS inputs are this orbit's OEF & STF. (And ABS if present.) ATS filename is of the format IBEX_yyyy_doy_o0xxxa_v0zz.scr. where IBEX is capitalized, yyyy is the year, doy is the day of year, xxx is the 3-digit orbit number and zz is the 2-digit version number. Any special operations ATSs will have another designation between the orbit number and version number (i.e. *00186a_hgc_v001 for the Hi gain curve). 	06/09/18	NGA

	Τ.			
Eclipses	1.	Check OEF for eclipses during the orbit.	N/A	
	2.	Verify long eclipse flag start & stop times reflect Ryan Tyler's recommendations based on his eclipse diagnostic tool. Suggestions made by Ryan after the use of this tool trump the general guidelines below.		
		(Please note, specific timing may shift if the recommendations are relative to eclipse timing. For example,		
		it may say set LE flag to false X hours after the end of the eclipse with a given FALSE time suggested. If		
		the eclipse timing changes as the ephemeris becomes more refined, this command time may shift.)		
	3.	Verify no contacts planned during an eclipse. Note: If in conflict, the eclipse diagnostic recommendations		
		will trump the general guidelines below.		
		 a Verify transmitter OFF from 30 minutes before eclipse start through the end of the eclipse. b For an eclipse where the long eclipse flag is set, schedule a SOH contact directly following 		
		the end of the eclipse (or per Ryan's assessment).		
		c Set the LE flag according to Ryan's assessments.		
	4.	Verify no maneuver planned during an eclipse. Note: If in conflict, the eclipse diagnostic recommendations		
		will trump the general guidelines below.		
		a Verify no maneuver or cat bed heaters on from 3 hours before eclipse start through 3 hours		
		after eclipse end. b Verify no maneuver or cat bed heaters are on while the long eclipse flag is set.		
	5.	Verify the following additional constraints (from battery balancing section).		
		a Verify the first command sets the long eclipse flag to TRUE, the second command		
		sets the flag to FALSE.		
		b Verify P/L is in HVSTANDBY or HVENG.		
		c Verify no charging cycle within 2 hours of ASCENDING or DESCENDING macro		
		execution.		
		This applies to all eclipses, not just moderate or long eclipses.		
Moon In Lo	1.	Check OEF for Moon in Lo FOV events.	06/09/18	NGA
FOV		• MoonInLoFovStart 6/20/2018 13:49:59		
		• MoonInLoFovStop 6/24/2018 19:58:59		
	2.	Check for corresponding Moon in Lo FOV start commands in ATS (timing will not be exact).		
		• PMT_LVL 300 \$TIME=2018/06:20:13:50:06		
		• IF_STAR_ADJ 0 \$TIME=2018/06:20:13:50:08		
		• PMT_LVL 300 \$TIME=2018/06:21:03:06:52		
		• IF_STAR_ADJ 0 \$TIME=2018/06:21:03:06:54		
		• PMT_LVL 300 \$TIME=2018/06:24:08:03:35		
		• IF_STAR_ADJ 0 \$TIME=2018/06:24:08:03:37		
		• Note: if the Moon is closer than 30 Re, the PMT will be set to 250. The distance to the moon can be		
		found in the STF.		
	3.	Check for corresponding Moon in Lo FOV stop commands.		
		• IF_STAR_ADJ 250 \$TIME=2018/06:21:03:06:52		
		• PMT_LVL 800 \$TIME=2018/06:21:03:06:54		
		• IE STAD ADI 250 \$TIME=2010/06:24:15:40:50		
		• IF_STAR_ADJ 250 \$TIME=2018/06:24:15:49:59 • PMT_LVI_800 \$TIME=2018/06:24:15:50:01		
		PMT_LVL 800 \$TIME=2018/06:24:15:50:01 Note: if the Meen is still in the FOV at the time of DESCENDING, no Meen in Le FOV at an		
		Note: if the Moon is still in the FOV at the time of DESCENDING, no Moon in Lo FOV stop commands will be present in ATS. The values are recent to the default at payt set of ASCENDING.		
		commands will be present in ATS. The values are reset to the default at next set of ASCENDING		
	1	macros. If Moon in Lo FOV starts in area of ands in area by sheek Moon in Lo FOV Start commands recent after		
	4.	If Moon in Lo FOV starts in arc a & ends in arc b, check Moon in Lo FOV Start commands resent after apogee ASCENDING commands.		
	5.	If Moon in Lo FOV starts within apogee HVSTANDBY period, check Moon in Lo FOV Start commands		
	J.			•

Contact	1.	Verify STX on/off times, downlink rate against <i>Orbit_oXXX.txt</i> file.	06/09/18	NGA
Commands	2.	Verify contacts in the previous ATS have not been duplicated.	00,00,10	11011
	3.	Verify all currently planned contacts in Orbit_xxx.txt are in the ATS.		
	4.	Verify each contact contains the following 5 commands.		
		SetRelay stx,on		
		 SetDownlink2K (2K, 40K, 64K, 160K, or 320K) 		
		 SetBilevelOutputControlReg STXMODE_Strobe,ON 		
		SetBilevelOutputControlReg COHERENT,ON		
		SetRelay stx,off		
	5.	If contact is near an eclipse		
		 Verify transmitter OFF from 30 minutes before eclipse start through 30 minutes after eclipse end. 		
		b. If additional transmitter constraints exist, they will be captured in Ryan's recommendations.		
	6.	If an APL contact is being used for an SSR Dump, the data rate should be at least 160 ksps & the SSR DUMP_NEW command should be included in the contact commands. Commands in Orange should only be sent if the SSR pointers need to be reset this perigee. These commands should be separated by 2s and occur 2s after the SSR_DUMP_NEW command.		
		SetRelay stx,on		
		SetDownlink2K		
		SetBowninize SetBilevelOutputControlReg STXMODE_Strobe,ON		
		SetBilevelOutputControlReg COHERENT,ON		
		SetDownlink320K		
		• SSR DUMP NEW		
		• SSR_SET_RD_PTR 6500		
		• SSR_SET_WRT_PTR 6500		
		SetRelay stx,off		
SC State	1.	Transition to Science state will be first command of each ATS (at 14 Re).	06/09/18	NGA
Science: arc		• SetScState science \$TIME=2018/06:20:10:18:15		
a	2.	Lo science mode will be the next command (at 14 Re).		
		LO_SCIENCE_MODE NORMAL		
	3.	Verify no transition to Science again at the end of the ATS. The ATS commands go from 14 Re to 14 Re in		
	١.	each orbit.		
	4.	Verify the transition to Science commands for this orbit are not part of the previous ATS using		
	_	http://ibex.unh.edu/cgi-bin/ats.cgi		
	5.	Verify that the beginning of this ATS does not overlap with the end of the previous orbit's ATS using http://ibex.unh.edu/cgi-bin/ats.cgi .		
Payload	1.	Verify w/ Crossing Times report that it occurs about 15 Re ascending. The arc a ASCENDING commands	06/09/18	NGA
Mode		can start any time at or above 15 Re ascending.	00/09/18	NUA
HVSCI :	2.	Verify commanding takes ~ 24 minutes.		
arc a		 ASCENDING_PL1 \$TIME=2018/06:20:12:06:42 		
		ASCENDING_HI		
		SET_PARAMETER 1, TLM_RATE_SOH		
		SET_PARAMETER 4, HV_STEP_DWELL		
		SET_PARAMETER 3, HV_STEP_FRAC		
		HI_COL_NEG_LVL 1400		
		CEU_HI_CEM_1_LVL 1780		
		CEU_HI_CEM_2_LVL 1780		
		CEU_HI_CEM_3_LVL 1780		
		CEU_HI_CEM_4_LVL 1900		
		SET_PARAMETER 0, TLM_RATE_SOH		
		ASCENDING_PL2		
		ASCENDING_PL1		
		ASCENDING_LO		

IBEX Command Approval Checklist K. Fairchild

Payload Mode		Payload DESCENDING commands end 1.5h before thruster enable.	06/09/18	NGA
HVSTANDBY	2.	Verify commands take ~23 minutes to execute.		
: arc a		 DESCENDING_PL1 \$TIME=2018/06:24:03:56:35 		
		DESCENDING_LO		
		ASCENDING_PL2		
		DESCENDING_PL1		
		DESCENDING_HI		
		 DESCENDING_PL2 \$TIME=2018/06:24:04:19:25 		
SC State HK:	1.	Spacecraft Housekeeping command occurs 1h before thruster enable.	06/09/18	NGA
arc a		SetScState housekeeping \$TIME=2018/06:24:04:52:35	00/07/10	NON
	1.	Use this command sequence if an apogee inertial maneuver is used, otherwise skip to the 'Sun Precession	0.5/0.0/4.0	2161
Inertial Maneuver:		Maneuver: Apogee' sequence below.	06/09/18	NGA
Apogee .	2.	Verify Thruster enable command occurs within STF maneuver window.		
Apogee	3.	Verify no eclipse occurs from cat bed heater on through set FC mode Mission.		
	4.	Verify cat bed heaters come on 55 min before burn.		
		• CATBED_5N_HTR,ON \$TIME=2018/06:24:04:57:33		
	5.	Verify Kalman Filter input select is ground command & estimator update is disabled.		
		SetKFInputSelect GND_CMD, 0, 0, 0, 0		
		SetEstUpdateEnables ENABLE, DISABLE		
	6.	Verify in FC mode Burn.		
		SetFcMode burn		
	7.	Compare SetInrDir in ATS with pointing as defined in the Forecast STF & verify the vectors match.		
		• SetInrDir -0.009425,0.921504,0.388256		
		targetX:-0.0094250000000000 targetY:0.92150399999999999		
		targetZ:0.388255999999999		
	8.	Verify inertial maneuver chosen.		
		SetLrTarget ACS_INERTIAL		
	9.	Verify thrust time set to 11 min.		
		SetThrustTime 660 Visit No. 10 Page 10 P		
	10.	Verify thruster enable command matches RepointingManeuverStart time in OEF.		
		SetThrustEnable ENABLE \$TIME=2018/06:24:05:52:33 Page 1415-2416-2516-2516-2516-2516-2516-2516-2516-25		
	4.4	• RepointingManeuverStart 2018-06-24T05:52:33		
	11.	Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0.		
		SetThrustEnable DISABLE \$TIME=2018/06:24:06:02:33		
		SetHTRCmd CATBED_5N_HTR,OFF		
		• SetThrustTime 0		
	12.	Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission.		
		SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/06:24:06:17:43		
		 SetKFInputSelect STA_PCT_VALID, 43,28,33,48 		
		SetFcMode Mission		

	1	Use this command sequence in the event of an energy Sun manager		
Sun	1.	Use this command sequence in the event of an apogee Sun maneuver. Verify Thruster enable command occurs within STF maneuver window.	N/A	
Precession	2. 3.	Verify no eclipse occurs from cat bed heater on through set FC mode Mission.		
Maneuver:	3. 4.			
Apogee	4.	Verify cat bed heaters powered on 55 min before thruster enable.		
	-	CATBED_5N_HTR,ON Variety in EC made Durn and Sun target		
	5.	Verify in FC mode Burn and Sun target.		
		SetFcMode burn		
	_	SetLrTarget ACS_SUN		
	6.	Verify thrust time set to 16 min.		
		SetThrustTime 960		
	7.	Verify thruster enable command matches SunMvrBegin time in OEF.		
		SetThrustEnable ENABLE		
		• SunMvrBegin		
	8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC		
		mode Mission.		
		SetThrustEnable DISABLE		
		SetHTRCmd CATBED_5N_HTR,OFF		
		SetThrustTime 0		
		SetFcMode Mission		
aa a	1.	Spacecraft Science commands occur ~1h after thruster Disable.	0.6/0.0/1.0	NGA
SC State		• SetScState science \$TIME=2018/06:24:07:07:39	06/09/18	NGA
Science : arc		LO_SCIENCE_MODE NORMAL		
b	1.	Verify payload ASCENDING commands begin at least 1.5 hours after thruster DISABLE.		
Payload	2.	Verify commands take ~24 minutes to execute.	06/09/18	NGA
Mode		ASCENDING_PL1 \$TIME=2018/06:24:07:37:39		
HVSCI : arc		ASCENDING_HI		
b		SET_PARAMETER 1, TLM_RATE_SOH		
		SET_PARAMETER 4, HV_STEP_DWELL		
		SET_PARAMETER 3, HV_STEP_FRAC		
		HI_COL_NEG_LVL 1400		
		• CEU_HI_CEM_1_LVL 1780		
		CEU_HI_CEM_2_LVL 1780		
		CEU_HI_CEM_3_LVL 1780		
		CEU_HI_CEM_4_LVL 1900		
		 SET_PARAMETER 0, TLM_RATE_SOH 		
		• ASCENDING_PL2		
		ASCENDING_PL1		
		ASCENDING_LO		
		• ASCENDING_PL2 \$TIME=2018/06:24:08:01:27		
Payload Mode	1.	Verify w/ Crossing Times report that it occurs about 15 Re descending. The arc b DESCENDING	06/00/40	NG:
HVSTANDBY		commands can complete any time at or above 15 Re descending.	06/09/18	NGA
: arc b	2.	Verify commands take ~23 minutes to execute.		
		• DESCENDING_PL1 \$TIME=2018/06:28:18:12:05		
		DESCENDING_LO		
		ASCENDING_PL2		
		• DESCENDING_PL1		
		DESCENDING_FIT DESCENDING_HI		
		• DESCENDING_PL2 \$TIME=2018/06:28:18:34:55		
SC State HK:	1.	Verify with Crossing Times report that Transition to Housekeeping state occurs at 14 Re desc (or an hour	06/09/18	NGA
arc b		before the maneuver if the maneuver occurs less than 1 hour after 14 Re desc).	Maneuver	
		SetScState housekeeping \$TIME=2018/06:28:19:50:54	delayed until	
			after perigee	
			due to star	
			tracker	
	l		outage	

Inertial	1.	Use this command sequence if a perigee inertial maneuver is used, otherwise skip to the 'Sun Precession	06/09/18	NGA
Maneuver:	_	Maneuver: Perigee' sequence below.	CALD:	
Perigee	2.	Verify no eclipse occurs from cat bed heater on through set FC mode Mission.	SetInrDir	
	3.	Verify cat bed heaters come on 55 min before burn.	values in ATS are	
	_	• CATBED_5N_HTR,ON \$TIME=2018/06:29:10:25:46	slightly	
	4.	Verify in Housekeeping state.	different	
	5.	Verify Kalman Filter input select is ground command & estimator update is disabled.	from target	
		SetKFInputSelect GND_CMD, 0, 0, 0, 0	vector	
	_	SetEstUpdateEnables ENABLE, DISABLE N. IC. I. P.C. I. P. N. IC. I. P.C. I. P. N. IC. I. P. I. P. N. IC. I. P. I. P. N. IC. I. P. I. P. N. I. P. I.	values in	
	6.	Verify in FC mode Burn.	forecast	
	_	SetFcMode burn Command Cather Disign A TS suith to make the command STE & considerate contacts	STF. Due to	
	7.	Compare SetInrDir in ATS with target vector in the Forecast STF & verify the vectors match.	delay of	
		 SetInrDir -0.087068,0.917661,0.387709 targetX:-0.009425000000000000 targetY:0.92150399999999999 	maneuver by	
		targetz:0.388255999999999	star tracker	
	8.	Verify inertial maneuver chosen.	outage.	
	0.	SetLrTarget ACS_INERTIAL		
	9.	Verify thrust time set to 11 min.		
	٥.	SetThrustTime 660		
	10.	Verify thruster enable command matches RepointingManeuverStart time in OEF.		
		SetThrustEnable ENABLE \$TIME=2018/06:29:11:20:46		
		RepointingManeuverStart 2018-06-29T11:20:46		
	11.	Verify 10 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0.		
		SetThrustEnable DISABLE \$TIME=2018/06:29:11:30:46		
		• CATBED 5N HTR,OFF		
		SetThrustTime 0		
	12.	Verify 25 min after thrusters enabled: Static Z rate set, outage %valid set, FC mode Mission.		
		SetStaticZrate ESTIMATOR, 0.418 \$TIME=2018/06:29:11:45:56		
		SetKFInputSelect STA_PCT_VALID, 43,28,33,48 SetFAM		
		SetFcMode Mission		
Sun	1.	Use this command sequence in the event of a perigee Sun maneuver.	N/A	
Precession	2.	Verify Thruster enable command occurs within STF maneuver window.		
Maneuver:	3.	Verify no eclipse occurs from cat bed heater on through set FC Mode Mission.		
Perigee	4.	Verify cat bed heaters come on 55 min before burn.		
	5.	CATBED_5N_HTR,ON Variety in EC made Prom and Sun target.		
	3.	Verify in FC mode Burn and Sun target. • SetFcMode burn		
	6	SetLrTarget ACS_SUN Varies throat time set to 16 min		
	6.	Verify thrust time set to 16 min.		
	7.	SetThrustTime 960 Varies thrustes anable command matches SunMurposin time in OFF.		
	7.	Verify thruster enable command matches SunMvrBegin time in OEF. • SetThrustEnable ENABLE		
		SunMvrBegin		
	8.	Verify 15 minutes after thrusters enabled: thrusters disabled, cat bed heaters off, thrust time set to 0, FC	1	
	0.	mode Mission.	1	
		SetThrustEnable DISABLE		
		SetHTRCmd CATBED_5N_HTR,OFF		
		SetThrustTime 0		
		SetFcMode Mission		
Battery Cell	1.	There will be battery cell balancing every 2 out of 3 orbits. Battery cell balancing this orbit? Y	06/09/18	NGA
Balancing	2.	Verify charging cycle (Long eclipse flag=TRUE) is 90 minutes long.	1	
Č	3.	Verify the first command sets the long eclipse flag to TRUE, the second command sets the flag to	1	
	٠.	FALSE.		
	4.	Verify P/L is in HVSTANDBY or HVENG.	1	
	5.	Verify no charging cycle within 2 hours of ASCENDING or DESCENDING macro execution.	1	
	6.	Verify no charging cycle within 1 hour of maneuver.		
	7.	Verify no charging cycle during an eclipse.	1	

IBEX Command Approval Checklist K. Fairchild

Rev 16d Last update 06/05/2018

Cmd Violation 1. Review CCVR. If you have any questions Reply All to the ATS Approval email and ask the team. 06/09/18 NGA

Activity	Anomaly Response: Non-nominal burn	Date Completed	Completed By
	• If the maneuver has not occurred or the spacecraft pointing as designated by either the star tracker or coarse Sun sensor is off by more than 2 degrees from the expected pointing, an anomaly has occurred.		
	 If the spacecraft is in Contingency state all stored commands are flushed from the command queue. Follow standard anomaly process. 		
	• If the Sun maneuver did not occur and the spacecraft is in either Science or Housekeeping state follow the steps below.		
	 If a partial Sun maneuver has occurred and the spacecraft is in either Science or Housekeeping state follow the steps below. 		
	• Please note that there is no anticipated hardware damage associated with exceeding the 12.5 degree constraint; this constraint is in place because we should not exceed the largest pointing achieved thus		
	far in the mission. 1. If the payload is in HVSTANDBY, LVENG or OFF, and there are no commands loaded to bring it		
	to HVSCI voltages, no operational pointing constraints will be violated. Follow standard anomaly process.		
	 If the payload is in HVSCI mode or there are uploaded commands to bring the payload to HVSCI mode. 		
	a. Determine current off Sun pointing. If the off Sun angle has already exceeded 12.5 degrees, the MOC should notify the MOM and immediately send the DESCENDING		
	command suite in real-time, as described below. If this cannot be done in the contact		
	where the pointing anomaly was discovered, another contact will be planned as soon as		
	possible to execute these commands.		
	@CEU_MACRO_EXEC DESCENDING_PL1 (< 1 min) @CEU MACRO EXEC DESCENDING LO (~ 10 min)		
	@CEU MACRO EXEC DESCENDING HI (~ 8 min)		
	@CEU_MACRO_EXEC DESCENDING_PL2 (< 1 min)		
	Please note: The only scenario where hitting 12.5 degrees is expected is when a perigee		
	Sun precession maneuver is completely missed after an inertial apogee maneuver which occurs late in the maneuver window (near apogee + 10 hours).		
	b. If current Sun pointing is below 12.5 degrees, the ISOC should input ST Sun-pointing		
	angle into ibex_rotate to determine the Sun angle at the time of DESCENDING. Sun-Angle at payload DESCENDING		
	c. If 12.5 degrees is not exceeded by the time of DESCENDING, no payload-specific action is needed for this arc. Follow standard anomaly response process.		
	 If 12.5 degrees is exceeded by the time of DESCENDING, a new command set should be sent. 		
	 The ISOC will generate the new STF which has the DESCENDING commands executing early such that 12.5 degrees is not exceeded while the payload is in HVSCI. 		
	ii. The MOC will create an associated ATS.		
	iii. Approval is needed by the MOM, MOC & ISOC prior to upload.		
	iv. The MOC will assess whether an additional pass is needed in order to		
	upload the commands prior to exceeding the 12.5 degree constraint. The onboard DESCENDING commands do not need to be deleted.		